

BIBLIOGRAPHY

CANADIAN SUBAERIAL CHANNELIZED DEBRIS FLOWS

September 30, 2000

Compiled by D.F. VanDine, PEng/PGeo

VanDine Geological Engineering Limited
267 Wildwood Avenue, Victoria, BC, V8S 3W2

TABLE OF CONTENTS

Section	Page
Definition	2
A Alphabetical	3
B Single debris flow/creek studies/reports	20
C Regional studies/reports	23
D General Papers/Review Papers	27
E Initiation: Conditions, Frequencies	28
F Transportation and Deposition/Debris Fans	30
G Rheology	31
H Sedimentology	33
I Runout	35
J Study Methodology	36
K Mitigation	38
L Theses	40
M Field Guides/Field Trips	42
N Forestry-related Studies/Reports	43
O Debris flows mentioned in regional/general landslide studies/reports	45
P Consulting reports and/or government internal reports	49
Q Geographical region	52
Alberta	52
British Columbia	53
General	53
Region 1: South Coast (Lower Mainland, Southwest BC)	54
Region 2: Thompson-Okanagan (South Central BC)	60
Region 3: Kootenays (Southeast BC)	61
Region 4: Central/North East	62
Region 5: North West	63
Region 6: Vancouver Island	64
Manitoba	65
Newfoundland	65
Quebec	65
Yukon	66

Definition

Subaerial channelized debris flows (or simply "debris flows") are a type of landslide that involve water saturated, predominantly coarse-grained inorganic and organic material flowing rapidly down a steep, subaerial, confined pre-existing channel.

Section A Alphabetical (citations followed by an asterisk (*) may not necessarily be available to the public)

- Abrams, A. 1979. Present geological hazards and soil sensitivity to earthquake movement for the Lower Mainland Official Regional Plan review. British Columbia Ministry of Environment, Victoria, BC, 18p.
- Alley, N.F. and Thomson, B. 1978. Aspects of environmental geology, parts of Graham Island, Queen Charlotte Islands. British Columbia Ministry of Environment, Resource Analysis Branch, Victoria, BC.
- Anderson, B.C., Haigh, T.R. and Smith, C.D. 1992. Geogrid reinforced soil and lock-block debris deflector for transmission towers. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p331-338.*
- Askin, R.W. 1995. Mountain logging in coastal British Columbia: environmental mitigation using geotechnical principles. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p745-754.*
- Ayotte, D. and Hungr, O. In press. Calibration of a runout prediction model for debris flows and avalanches. *In Proceedings, 2nd International Conference on Debris Flow Hazard Mitigation, Taipei, Taiwan.*
- Ayotte, D., Evans, N. and Hungr, O. 1999. Runout analysis of debris flows and avalanches in Hong Kong. *In Proceedings, 13th Vancouver Geotechnical Society Symposium, Vancouver, BC, p39-46.*
- Bartle, H.T., Rollerson, T.P. and Thomson, B. 1997. Report on the May 31, 1997 Gowan Creek debris flow and fatality. Report to British Columbia Ministry of Forests, Squamish Forest District, 13 p.*
- Batterson, M., Liverman, D.G.E., Ryan, J. and Taylor, D. 1999. The assessment of geological hazards and disasters in Newfoundland: an update. Newfoundland Department of Mines and Energy, Geological Survey, Report 99-1:95-123.
- Baumann Engineering. 1997. Level II slide assessments, Hesquiat Lake, near Boat Basin, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Baumann Engineering. 1997. Level II slide assessments, Kanim Lake, near Hotsprings Cove, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Beaudoin, A.B. and King, R.H. 1994. Holocene palaeoenvironmental record preserved in a paraglacial alluvial fan, Sunwapta Pass, Jasper National Park, Alberta, Canada.. *Catena, 22(3):227-248.*
- Benvenuti, M. and Martini, P. 1997. Sedimentological facies analysis on alluvial, highly concentrated-flow deposits. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p496-505.*
- Bovis, M.J. 1993. Hillslope geomorphology and geotechnique. *Progress in Physical Geography, 17(2):173-189.*
- Bovis, M.J. and Dagg, B.R. 1988. A model for debris accumulation and mobilization in steep mountain streams. *Journal of Hydrological Sciences, 33(6):589-604.*
- Bovis, M.J. and Dagg, B.R. 1992. Debris flow triggering by impulsive loading: mechanical modelling and case studies. *Canadian Geotechnical Journal, 29(3):345-352.*
- Bovis, M.J. and Jakob, M. 1999. The role of debris supply conditions in predicting debris flow activity. *Earth Surface Processes and Landforms, 24(11):1039-1054.*

- Bovis, M.J. and Jakob, M. In press. The July 30, 1998 debris flow and landslide dam at Capricorn Creek, Mount Meager Volcanic Complex, British Columbia. *Canadian Journal of Earth Sciences*.
- Bovis, M.J. and Millard, T.H. 1992. Precipitation thresholds for debris flow initiation in the southern Coast Mountains of British Columbia. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p309.*
- Bovis, M.J., Dagg, B.R. and Kaye, D. 1985. Debris flows and debris torrents in the southern Canadian Cordillera: discussion. *Canadian Geotechnical Journal*, 22(4):608.
- Boyer, D. 1999. Debris flow hazards on alluvial fans: Kootenay Region, southeast BC. *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC, p325-327.*
- Brardinoni, F. In prep. The frequency distribution of small debris flows in the Capilano River basin. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Brayshaw, D.D. 1997. Factors affecting post-logging debris flow initiation in steep forested gullies of the southwestern Canadian Cordillera, Fraser Valley region. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Brevik, E.C. and Reid, J.R. 1993. Evidence for catastrophic debris flow in southern Manitoba. *In Proceedings, North Dakota Academy of Science, 47:46.*
- British Columbia Environment and Land Use Secretariat. 1980. Howe Sound, an overview study. Victoria, BC, 131p.
- British Columbia Ministry of Forests. 1995. Gully assessment procedure guidebook. Forest Practices Code of British Columbia, Victoria, BC.
- British Columbia Ministry of Transportation and Highways. 1996. Natural hazards recognition manual. Geotechnical Engineering and Materials Branch, Victoria, BC.
- Brooks, G.R. 1992. Aspects of post-glacial sediment supply and its control upon the morphology of the Squamish River, southwestern British Columbia. PhD thesis, Simon Fraser University, Department of Geography, Burnaby, BC, 448 p.
- Broscoe, A.J. and Thomson, S. 1969. Observations on an alpine mudflow, Steele Creek, Yukon. *Canadian Journal of Earth Science*, 6:219-229.
- Buchanan, P. and Savigny, K.W. 1990. Factors controlling debris avalanche initiation. *Canadian Geotechnical Journal*, 27:659-675.
- Buchanan, P., Savigny, K.W. and De Vries, J. 1990. A method for modelling water tables at debris avalanche headscarps. *Journal of Hydrology*, 113:61-88.
- Buchanan, R. and Abrams, A. 1979. Preliminary geological hazards – Howe Sound. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Carr, K. 1989. Debris flow hazard in the Cathedral Mountain area, Kicking Horse Pass, British Columbia: causes, effects and response to the risk. Undergraduate paper, Wilfred Laurier University, Department of Earth Sciences, Waterloo, ON, 32p.
- Carson, B.R., Thomson, B., Hogan, D. and Bates, D. 1998. Slope failures, water quality and stream channel morphology: a case study. *In Proceedings, 8th Congress International Association of Engineering Geology and the Environment, Vancouver, BC. D. Moore and O. Hungr (editors), p2017-2024. Section B, C, D, N*
- Cass, D.E., Kenning, B.F.I. and Rawlings, G. 1992 The Philpott Road debris failures – Kelowna, BC, 1990. the impacts of geology, hydrology and logging activities. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p319-330.*

- Chatwin, S.C. and Smith, R.B. 1992. Reducing soil erosion associated with forestry operations through integrated research: an example from coastal British Columbia, Canada. *In* Proceedings, Erosion, Debris Flows and Environment in Mountain Regions, IASG Publication, 209:377-385.
- Chatwin, S.C., Howes, D.E., Schwab, J.W. and Swanston, D.N. 1994. A guide for management of landslide-prone terrain in the Pacific Northwest. 2nd edition. British Columbia Ministry of Forests, Land Management Handbook 18, 220p.
- Church, M. 1984. Debris torrents and natural hazards of steep channels: east shore of Howe Sound. Field Trip 7 Guidebook. Canadian Association of Geographers Annual Meeting, Nanaimo, British Columbia. University of British Columbia, Department of Geography, 83p.
- Church, M. 1985. Debris torrents and natural hazards of steep mountain channels: east shore of Howe Sound. Field-Trip 4 Guidebook. *In* Jackson, Jr. L.E., Church, M., Clague, J.J. and Eisbacher, G.M. Slope hazards in the southern Coast Mountains of British Columbia. Geological Society of America, Cordilleran Section Annual Meeting, Vancouver, BC.
- Church, M. and Desloges, J.R. 1984. Debris torrents and natural hazards of steep mountain channels: east shore of Howe Sound: University of British Columbia, Department of Geography, Vancouver, BC, 83p.
- Church, M. and Miles, M.J. 1987. Meteorological antecedents to debris flow in southwestern British Columbia: some case studies. *In* Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation, Reno, NV. J.E. Costa and G.F. Wieczorek (editors). Reviews in Engineering Geology 7, Geological Society of America, Boulder, CO, p63-79.
- Church, M. and Russell, S.O.D. 1983. Recent history and condition of Alberta Creek at Lions Bay, British Columbia: implications for the safety of settlement at Lions Bay. University of British Columbia, Vancouver, BC, internal report.
- Church, M. and Ryder, J.M. 1989. Sedimentology and clast fabric of subaerial debris flow facies in a glacially-influenced alluvial-fan: discussion. *Sedimentary Geology*, 65(1):195-196.
- Clague, J.J. 1978 Terrain hazards in the Skeena and Kitimat River basins, British Columbia. Geological Survey of Canada, Paper 78-1A, p183-188.
- Clague, J.J. 1981. Landslides at the south end of Kluane Lake, Yukon Territory. *Canadian Journal of Earth Sciences*, 18(5):959-971.
- Clague, J.J. 1987. Catastrophic outburst floods. *Geoscience Canada*, 16(2):18-21.
- Clague, J.J., Evans, S.G. and Blown, I.G. 1985. A debris flow triggered by the breaching of a moraine-dammed lake, Klattasine Creek, British Columbia. *Canadian Journal of Earth Sciences*, 22(10):1492-1502.
- Couture, R. and Evans, S.G. 2000. Five-Mile Creek debris flow, Banff National Park, near Banff, Alberta, August 4th, 1999. Geological Survey of Canada, Open File 3876.
- Couture, R. and Evans, S.G. 2000. The East Gate landslide, Beaver Valley, Glacier National Park, Columbia Mountains, British Columbia. Geological Survey of Canada, Open File 3877.
- Cruden, D.M. 1985. Rock slope movements in the Canadian Cordillera. *Canadian Geotechnical Journal*, 22:528-540.
- Cruden, D.M. and Lu, Z.Y. 1989. The geomorphic impact of the catastrophic October 1984 flood, on the platform of the Spanish River, southwest British Columbia. *Canadian Journal of Earth Sciences*, 26:336.
- Cruden, D.M. and Lu, Z.Y. 1992. The rockslide and debris flow from Mount Cayley, BC, in June 1984. *Canadian Geotechnical Journal*, 29(4):614-626.
- Currie, M.V., Skermer, N.A., and West-Sells, R.J. 1996. Debris flow hazard mitigation at Upper Mackay Creek, North Vancouver. *In* Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC.

- Currie, M.V., Skermer, N., Jakob, M. and West-Sells, B. 1999. Debris flow hazards in North Vancouver District: how do we manage the risk? *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC, p12-14.*
- Curry, G.E. and Mann, A.S. 1965. Estimating precipitation in a remote headwater area of western Alberta. *In Proceedings, 33rd Annual Meeting of the Western Snow Conference, Colorado Springs, CO, p58-66.*
- Dagg, B.R. 1987. Debris supply torrent-prone channels on the east side of Howe Sound, British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Davidson, S.C. 1998. Hydrologic controls of landsliding in Tsitika basin, Vancouver Island. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Desloges, J.R. 1982. Sedimentology and paleohydrology of alpine multiple-process channels in southwestern Alberta. Masters thesis, University of Wisconsin, Department of Geography, Madison, WI, 216p.
- Desloges, J.R. and Gardner, J.S. 1984. Process and discharge estimation in ephemeral channels, Canadian Rocky Mountains. *Canadian Journal of Earth Sciences, 21:1050-1060.*
- Dumoulin, J. 1965. Her Majesty the Queen vs. Canadian Pacific Railway Company, Twin Butte mudslide judgement. Exchequer Court of Canada, Victoria, BC, 29p.
- EBA Engineering Consultants Ltd. 1996. Debris flow initiation potential, gully assessment procedures, and meteorological conditions associated with debris flows in the Kalum Forest District, northwestern British Columbia. Report to Ministry of Forests, Prince Rupert Region, 32p.*
- EBA Engineering Consultants Ltd. 1998. Hillside industrial park debris flow, debris flood and landslide hazard assessment, Port Mellon, BC. Report to Sunshine Coast Regional District.*
- EBA Engineering Consultants Ltd. 1998. History of debris floods on Susap Creek fan, lower Similkameen Valley. Report to Canada Department of Indian and Northern Affairs, Vancouver, BC.*
- EBA Engineering Consultants Ltd. 1999. Clementine Creek debris flow investigation. Report to Burrard Yacht Club, Vancouver, BC.*
- EBA Engineering Consultants Ltd. 2000. Deroche Creek debris flow and debris flood study. Report to Fraser Valley Regional District.*
- Eisbacher, G.H. 1979. First order regionalization of landslide characteristics in the Canadian Cordillera. *Geoscience Canada, 6(2):69-79.*
- Eisbacher, G.H. 1982. Slope stability and land use in mountain valleys. *Geoscience Canada, 9:14-27.*
- Eisbacher, G.H. 1982. Howe Sound debris flows. *Geoscience Canada, 9(2):132.*
- Eisbacher, G.H. 1982. Mountain torrents and debris flows. *Episodes, 4(1):12-17.*
- Eisbacher, G.H. 1983. Slope stability and mountain torrents, Fraser lowland and southern Coast Mountains, British Columbia. *Field Trip Guidebook 15. Geological Association of Canada Meeting, Victoria, BC.*
- Eisbacher, G.H. and Clague, J.J. 1981. Urban landslides in the vicinity of Vancouver, British Columbia, with special reference to the December 1979 rainstorm. *Canadian Geotechnical Journal, 18:205-216.*
- Eisbacher, G.H. and Clague, J.J. 1984. Destructive mass movements in high mountains: hazard and management. *Geological Survey of Canada, Paper 84-16, 230p.*
- Evans, S.G. 1982. Landslides and surficial deposits in urban areas of British Columbia: a review. *Canadian Geotechnical Journal, 19:269-288.*

- Evans, S.G. and Clague, J.J. 1989. Rain-induced landslides in the Canadian Cordillera, July 1988. *Geoscience Canada*, 16:193-200.
- Evans, S.G. and Clague, J.J. 1997. The impact of climate change on catastrophic geomorphic processes in the mountains of British Columbia, Yukon and Alberta. *In* Responding to Global Climate Change in British Columbia and Yukon. Volume 1 of the Canada Country Study: Climate Impacts and Adaptation. E. Taylor and B. Taylor (editors). British Columbia Ministry of Environment, Lands and Parks and Environment Canada, Vancouver, BC, p7:1-7:16.
- Evans, S.G. and Lister, D.R. 1984. The geomorphological effects of the July 1983 rainstorms in the southern Cordillera and their impact on transportation facilities. *Geological Survey of Canada*, Paper 84-1B, p223-235.
- Evans, S.G. and Savigny, K.W. 1994. Landslides in the Vancouver - Fraser Valley - Whistler region. *In* Geology and Geological Hazards of the Vancouver Region, Southwestern British Columbia. J.W.H. Monger (editor). Geological Survey of Canada, Bulletin 481, p251-286.
- Evans, S.G., Hungr, O. and Clague, J.J. In press. The 1984 rock avalanche from the western flank of Mt. Cayley, British Columbia: description and dynamic analysis of a hyper-mobile landslide. *Engineering Geology*.
- Eyles, N. 1987. Late Pleistocene debris-flow deposits in large glacial lakes in British Columbia and Alaska. *Sedimentary Geology*, 53(1-2):33-71.
- Eyles, N. and Clague, J.J. 1987. Landsliding caused by Pleistocene glacial lake ponding - an example from central British Columbia. *Canadian Geotechnical Journal*, 24(4):656-663.
- Eyles, N. and Kocsis, S. 1988. Sedimentology and clast fabric of subaerial debris flow fan facies in a glacially-influenced alluvial fan. *Sedimentology*, 59:15-28.
- Eyles, N., Eyles, C.H. and McCabe, A.M. 1988. Late Pleistocene subaerial debris-flow facies of the Bow Valley, near Banff, Canadian Rocky Mountains. *Sedimentology*, 35:465-480.
- Fannin R.J. and Jaakkola, J.J. 1999. Hydrological response of hillslope soils above a debris-slide headscarp. *Canadian Geotechnical Journal*, 36(6):1111-1122.
- Fannin, R.J. and Rollerson, T.P. 1993. Debris flows: some physical characteristics and behaviour. *Canadian Geotechnical Journal*, 30(1):71-81.
- Fannin, R.J. and Wilkinson, J.M.T. 1995. An analysis of the Jaminson Creek landslide. *In* Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p635-642.
- Fannin, R.J. and Wise, M.P. 1995. Method for calculation of debris flow travel distance. *In* Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p643-650.
- Fannin, R.J., Jaakkola, J., Wilkinson, J.M.T. and Hetherington, E.D. In press. The hydrological response of soils to rainfall at Carnation Creek, British Columbia. *Water Resources Research*.
- Fannin, R.J., Rollerson, T.R., Hogan, D.L. and Daust, D. 1992. Characteristics of a large debris flow channel. *In* Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p311-318.
- Fannin, R.J., Wise, M.P., Wilkinson, J.M.T., Thomson, B. and Hetherington, E.D. 1997. Debris flow hazard assessment in British Columbia. *In* Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p197-206.
- Friele, P.A., Ekes, C. and Hickin, E.J. 1999. Evolution of Cheekeye fan, Squamish, British Columbia: Holocene sedimentation and implications for hazard assessment. *Canadian Journal of Earth Sciences*, 36:2023-2031.

- Galay, V.J., Rood, K. and Hungr, O. 1992. Dynamics of hazards within watersheds. *In* Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p299-307.
- Gardner, J.S. 1981. Ephemeral and episodic transport of debris on mountain slopes. Progress Report on Research Conducted Under Permit from Parks Canada, Western Region Parks Canada, Calgary, AB, 22p.
- Gardner, J.S. 1982. Alpine mass-wasting in contemporary time, some examples from the Canadian Rocky Mountains. *In* Proceedings, Space and Time in Geomorphology, Binghamton Symposium. C.E. Thorn (editor). International Series 12, George Allen and Unwin, p171-192.
- Gardner, J.S. 1986. Sediment movement in ephemeral streams on mountain slopes, Canadian Rocky Mountains. *In* Proceedings, Hillslope Processes, Binghamton Symposia in Geomorphology. A.D. Abraham (editor). International Series 16, Allen & Unwin Inc, Winchester, p97-113.
- Gimbarzevsky, P. 1988. Mass wasting on the Queen Charlotte Islands - a regional inventory. British Columbia Ministry of Forests, Land Management Report 29, 96p.
- Golder Associates Ltd. 1962. Landslide on Canadian Pacific Railway at Twin Butte, British Columbia. Report to Canadian Wheat Board.*
- Golder Associates Ltd. 1990. Debris torrent hazard assessment kilometre 1020, Floods, BC. Report to Trans-Mountain Pipeline Company Ltd, Vancouver, BC.*
- Golder Associates Ltd. 1990. Philpott Road potential for slides and debris flows, Kelowna. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Golder Associates Ltd. 1995. Runout characteristics of debris from dump failures in mountainous terrain. Stage 2: analysis, modelling and prediction. Report to the British Columbia Mine Waste Rock Pile Research Committee and CANMET, 55p.
- Gottesfeld, A.S., Mathewes, R.W., Johnson, and Gottesfeld, L.M. 1991. Holocene debris flows and environmental history, Hazelton area, British Columbia. *Canadian Journal of Earth Sciences*, 28(10):1583-1593.
- Grainger, W. 1999. Investigation of 22 landslides in Upper Chase Creek, BC. *In* Proceedings, 13th Vancouver Geotechnical Society Symposium, Vancouver, BC, p97-106.
- Gustafson, C.A. 1985. Debris flows along the Slims River valley, Kluane National Park, Yukon Territory. Masters thesis, University of Calgary, Calgary, AB.
- Hardy, R.M., Morgenstern, N.R. and Patton, F.D. 1978. Report of the Garibaldi "the Barrier" Advisory Panel (3 parts). British Columbia Department of Highways, Victoria, BC, 321p.*
- Harris, S.A. and Gustafson, C.A. 1988. Retrogressive slumps, debris flows and river valley development in icy, unconsolidated sediments on hills and mountains. *Zeitschrift fur Geomorphologie*, 32(4):441-455.
- Harris, S.A. and Gustafson, C.A. 1993. Debris flow characteristics in an area of continuous permafrost, St. Elias Range, Yukon Territory. *Zeitschrift fur Geomorphologie*, 37(1):41-56.
- Harris, S.A. and McDermid, G. 1998. Frequency of debris flows on the Sheep Mountain fan, Kluane Lake, Yukon Territory. *Zeitschrift fur Geomorphologie*, 42(2):159-175.
- Hawley, P.M. 1989. Identification, evaluation and mitigation of debris flow hazards in British Columbia. *In* Proceedings, Conference XX, International Erosion Control Association, Vancouver, BC, p471.
- Hogan, D.L. 1986. Channel morphology of unlogged, logged, and debris torrented streams in the Queen Charlotte Islands. British Columbia Ministry of Forests and Lands, Land Management Report 49, Victoria, BC, 94p.

- Hogan, D.L. and J.W. Schwab. 1991. Meteorological conditions associated with hillslope failures on the Queen Charlotte Islands. British Columbia Ministry of Forest, Land Management Report 73, Victoria, BC.
- Hogan, D.L., Bird, S.A. and Rice, S. 1998. Stream channel morphology and recovery processes. *In* Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions. D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Howes, D.E. 1981. Terrain inventory and geological hazards: northern Vancouver Island. British Columbia Ministry of Environment, Assessment and Planning Division, APD Bulletin 5, Victoria, BC.
- Howes, D.E. 1987. A terrain evaluation method for predicting terrain susceptible to post-logging landslide activity. British Columbia Ministry of Environment, Technical Report 28, Victoria, BC, 38p.
- Hungr, O. 1985. Transport mechanisms in debris flows of the Canadian Cordillera. Geological Society of America, Boulder, CO, Abstracts with Program, 17:362.
- Hungr, O. 1988. Notes on dynamic analysis of flowslides. *In* Proceedings, 5th International Symposium on Landslides, Lausanne, Switzerland, p679-683.
- Hungr, O. 1990. A mass change model for the estimation of debris flow runout: discussion. *Journal of Geology*, 99:633-634.
- Hungr, O. 1992. Runout prediction for flow-slides and avalanches: analytical methods. *In* Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p139-144.
- Hungr, O. 1993. Mass-referenced flow model for dynamic analysis of flow slides and avalanches. Invited paper *in* Proceedings, "Pierre Beghin" International Workshop on Rapid Gravitational Movements, Grenoble University press, p145-151.
- Hungr, O. 1993. Flood and debris flow mitigation for the proposed Whistler Creek redevelopment. *In* Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC, p97-103.
- Hungr, O. 1995. A model for the runout analysis of rapid flow slides, debris flows and avalanches. *Canadian Geotechnical Journal*, 32(4):610-623.
- Hungr, O. 1997. Analysis of the motion of a debris avalanche event. *Chikyū* ("Earth") magazine, Japan, special issue focused on debris flow hazards. H.Fukuoka (editor), 19:661-665 (translated into Japanese).
- Hungr, O. *In press*. Analysis of debris flow surges using the theory of uniformly progressive flow. *Earth Surface Processes and Landforms*.
- Hungr, O. and Evans, S.G. 1997. A dynamic model for landslides with changing mass. *In* Proceedings, Symposium on Engineering Geology and the Environment, International Association of Engineering Geology, Athens, Greece, p719-724.
- Hungr, O. and Evans, S.G. 1984. An example of a peat flow near Prince Rupert, British Columbia. *Canadian Geotechnical Journal*, 22:246-249.
- Hungr, O. and Jackson, Jr. L.E. 1992. A debris flow basin and event data base format with an example data set from southwestern British Columbia. Geological Survey of Canada, Open File Report 2522, 12p.
- Hungr, O. and McClung, D.M. 1987. An equation for calculating snow avalanche run-up against barriers. *In* *Avalanche Formation, Motion and Effects*, IAHS Publication 162, p605-612.
- Hungr, O. and Morgenstern, N.R. 1984. Experiments in high velocity open channel flow of granular materials. *Géotechnique*, 34: 405-413

- Hungr, O. and Morgenstern, N.R. 1984. Experiments in high velocity open channel flow of granular materials: reply. *Géotechnique*, 35: 383-385.
- Hungr, O. and Morgenstern, N.R., 1984. High velocity ring shear tests on sand. *Géotechnique*, 34:415-421.
- Hungr, O. and Rawlings, G. 1995. Terrain hazards assessment for planning purposes: Cheekeye Fan, BC. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p509-517.*
- Hungr, O. and Skermer, N. 1992. Debris torrents and rockslides, Howe Sound to Whistler corridor. *Field Trip Guidebook, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers.*
- Hungr, O. and Smith, D. 1985. Landslides and development in the lower mainland, British Columbia. *BC Professional Engineer, Vancouver, BC, 36:11-14.*
- Hungr, O., Morgan, G.C. and Kellerhals, R. 1984. Quantitative analysis of debris torrent hazards for the design of remedial measures. *Canadian Geotechnical Journal, 21:663-677.*
- Hungr, O., Sobkowicz, J.C. and Morgan, G.C. 1993. How to economize on natural hazards. *Geotechnical News, 11:54-57.*
- Hungr, O., Evans, S.G., Bovis, M.J and Hutchinson, J.N. In press. A review of the classification of landslides of the flow type. *Environmental and Engineering Geoscience*
- Hungr, O., Morgan, C.C., VanDine, D.F. and Lister, D.R. 1987. Debris flow defenses in British Columbia. *In Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation, Reno, NV. J.E. Costa and G.F. Wieczorek (editors). Reviews in Engineering Geology 7, Geological Society of America, Boulder, CO, p63-79.*
- Hungr, O., Dawson, R., Kent, A., Campbell, D. and Morgenstern, N.R., In press. Rapid flow slides of coal mine waste in British Columbia, Canada. *In Catastrophic Landslides, Reviews in Engineering Geology, Geological Society of America, Boulder, CO.*
- Hungr, O., Yau, H.W., Tse, C.M., Cheng, L.F. and Hardingham, A.D. 1998. Natural slope hazard and risk assessment framework. *In Proceedings, International Conference on Urban Ground Engineering, Hong Kong. Institute of Civil Engineers.*
- Jaakkola, J.J. 1998. Forest groundwater hydrology: implications for terrain stability in coastal British Columbia. *Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.*
- Jaakkola, J.J. and Fannin, R.J. 1999. Analysis of hillslope piezometric records: implications for terrain stability. *In Proceedings, 13th Annual Vancouver Geotechnical Society Symposium, Vancouver, BC, p671-680.*
- Jackson, Jr., L.E. 1979. A catastrophic glacial outburst flood (jokulhlaup) mechanism for debris flow generation at the Spiral Tunnels, Kicking Horse River basin, British Columbia. *Canadian Geotechnical Journal, 16(4):806-813.*
- Jackson, Jr., L.E. 1979. Mystery flood solved: CPR records revealed the 1978 catastrophe was not unique. *Geos, 8(3):2-4.*
- Jackson, Jr., L.E. 1980. New evidence in the origin of the September 6, 1978 jokulhlaup from the Cathedral Glacier. *Geological Survey of Canada, Paper 80-1B, p292-294.*
- Jackson, Jr., L.E. 1987. Debris flow hazard in the Canadian Rocky Mountains, *Geological Survey of Canada, Paper 86-11, 10p.*
- Jackson Jr, L.E. 1996. Slope hazards investigation trip to Kicking Horse Pass, British Columbia. *Informal field trip guidebook, Vancouver, BC.*
- Jackson, Jr., L.E., Kostaschuk, R.A. and MacDonald, G.M. 1987. Identification of debris flow hazard on alluvial fans in the Canadian Rocky Mountains. *In Proceedings, Debris*

- Flows/Avalanches: Process, Recognition and Mitigation, Reno, NV. J.E. Costa and G.F. Wieczorek (editors). *Reviews in Engineering Geology* 7, Geological Society of America, Boulder, CO, p115-124.
- Jackson, Jr., L.E., Hungr, O., Gardner, J.S. and MacKay, C. 1989. Cathedral mountain debris flows, Canada. *Bulletin International Association of Engineering Geology*, 40:35-54.
- Jacob, N. 2000. Debris flow activity in a forest environment, Gaspésie, Québec: triggering, frequency and magnitude. Masters thesis, Université Laval, Department of Geography (Centres d'Études Nordiques), Laval QU, 96p.
- Jakob, M. 1996. Morphometric and geotechnical controls of debris flow frequency and magnitude in southwestern British Columbia. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Jakob, M. 1996. Debris flows - curse of the mountains. *Geography Review*, 9(5):34-36.
- Jakob, M. 1999. The impacts of logging on landslide activity at Clayoquot Sound, Vancouver Island, British Columbia. *Catena* 38(4):279-300.
- Jakob, M. 2000. Trees, water and soil - landslides in British Columbia. *Geography Review* 13(3):12-15.
- Jakob, M. and Bovis, M.J. 1996. Morphometric and geotechnical controls of debris flow activity, southern Coast Mountains, British Columbia, Canada. *Zeitschrift fur Geomorphologie, N.F.*, 104:13-26.
- Jakob, M. and Podor, A. 1995. Frequency and magnitude of debris flows. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society*, p491-498.
- Jakob, M. and Skermer, N. [translators]. 1997. Debris flow. Translation from German of J. Stiny, Die Muren, 1910. EBA Engineering Consultants Ltd, Vancouver, BC, 105p.
- Jakob, M., Hungr, O. and Thomson, B. 1997. Two debris flows with anomalously high magnitude. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York*, p382-394.
- Jakob, M., Martin, S., Skermer, N., Campbell, C., Anderson, D. and Fuller, T. 1998. A record breaking debris flow at Hummingbird Creek, Mara Lake, BC. *In Proceedings 8th Congress International Association of Engineering Geology and the Environment, Vancouver, BC. D. Moore and O. Hungr (editors)*, p2091-2098.
- Jakob, M., Hungr, O., Anderson, D., Fuller, T. and Ayotte, D. In press. The July 7, 1997 debris flow at Hummingbird Creek. *Canadian Geotechnical Journal*.
- Jones, N.K. 1987. Debris transport and deposition at Boundary Glacier, Banff National Park, Alberta. PhD thesis, University of Waterloo, Waterloo, ON.
- Jones, W.C. 1959. Cheekeye River mudflows. British Columbia Department of Mines, Victoria, BC, memorandum, 9p.
- Jordan, P. 1987. Impacts of mass movement events on rivers in the southern Coast Mountains, British Columbia: summary report. Report to Environment Canada, Inland Waters Directorate, Sediment Survey IWD-HQ-WRB-SS-87-3.
- Jordan, P. 1990. Large debris flows in the Meager Creek volcanic complex, British Columbia. *Eos*, 71:1145. (Paper presented at American Geophysical Union, Pacific Northwest regional meeting, Seattle.)
- Jordan, P. 1991. Dynamic behavior and material properties of debris flows in the southern Coast Mountains, British Columbia. *In Program with Abstracts, Geological Association of Canada Annual Meeting, Vancouver BC*, pA66.

- Jordan, P. and Slaymaker, O. 1991. Holocene sediment production in Lillooet River basin, British Columbia: a sediment budget approach. *Geographie physique et Quaternaire*, 45(1):45-57.
- Jordan, R.P. 1995. Debris flows in the southern Coast Mountains, British Columbia: dynamic behaviour and physical properties. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Kerr Wood Liedal Ltd./EBA Engineering Consultants Ltd. 1999. Overview report on debris flow hazards. Report to District of North Vancouver, BC.*
- Klohn Leonoff Ltd. 1992. Debris torrents. *In* Functional Design Study of the Sea to Sky Highway. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC.*
- Klohn Leonoff Limited. 1994. Flood hazard management plan. Report to the Regional District of Squamish, BC.*
- Klohn-Crippen Consultants Ltd. 1998. Terrain stability inventory - alluvial and debris torrent fans, Kootenay Region. Report to British Columbia Ministry of Environment Lands and Parks, Kootenay Region.*
- Kostaschuk, R.A., MacDonald, G.M. and Jackson, Jr., L.E. 1987. Rocky Mountain alluvial fans. *The Canadian Geographer*, 31(4):366-368.
- Kostaschuk, R.A., MacDonald, G.M. and Putman, P. 1986. Depositional process and alluvial fan-drainage basin morphometric relationships near Banff, Alberta. *Earth Surface Processes and Landforms*, 11:471-484.
- Krag, R.K., Sauder, E. A. and Welburn, G.V. 1986. A forest engineering analysis of landslides in logged areas on the Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Land Management Report 43, Victoria BC, 138p.
- Lister, D.R. 1983. Chilliwack to Hope debris torrents, near Wahleach. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lister, D.R. 1988. Litigation resulting from debris torrent activity along Howe Sound. *In* Proceedings, Risk and Liability in Geotechnical Engineering, Vancouver Geotechnical Society, Vancouver, BC.
- Lister, D.R. 1988. Slovan Lake (north end) potential debris flow. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lister, D.R. 1991. Debris torrent 33km north of Sayward. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lister, D.R. and Morgan, G.C. 1989. Debris torrents along Howe Sound, British Columbia. Field Trip Excursion Guidebook. Conference XX, International Erosion Control Association, Vancouver, BC.
- Lister, D.R., Morgan, G.C., VanDine, D.F. and Kerr, J.G.W. 1984. Debris torrents in Howe Sound, British Columbia. *In* Proceedings, 4th International Symposium on Landslides, Toronto ON, p649-654.
- Locat, J. 1992. Viscosity, yield strength, and mudflow mobility for sensitive clays and other fine sediments. *In* Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p389-396.
- Locat, J. 1997. Normalized rheological behaviour of fine muds and their flow properties in a pseudoplastic regime. *In* Proceedings, 1st International Conference on Debris-flow Hazard

- Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p260-269.
- Locat, J. and Cruden, D.M. 1977. Major landslides in the eastern slopes of the southern Canadian Rockies. *In Proceedings, 15th Annual Idaho Symposium on Engineering Geology and Soils, Boise, ID, p179-197.*
- Lu, Z.Y. 1992. Prehistoric debris avalanches from Mount Cayley volcano, British Columbia: discussion. *Canadian Journal of Earth Sciences, 29:1342-1343.*
- Lu, Z.Y. 1993. Landslides and geotechnical properties of volcanic tuff on Mount Cayley, British Columbia. PhD thesis, University of Alberta, Department of Civil Engineering, Edmonton, AB, 263p.
- Lu, Z.Y. and Cruden, D.M. 1996. Two debris flow modes on Mount Cayley, British Columbia. *Canadian Geotechnical Journal, 32(1):123-139.*
- Lu, Z.Y. and Cruden, D.M. 1998. Velocity-dependent local phenomena around an extremely rapid landslide. *In Proceedings, 8th Congress of the International Association of Engineering Geology, Vancouver, BC, p1431-1436.*
- Martin, D.C. 1989. Remedial measures for debris flows in British Columbia. *Bulletin Association of Engineering Geology, 25:265-276.*
- Martin, D.C., Piteau, D.R., Pearce, R.A. and Hawley, P.M. 1984. Remedial measures for debris flows at the Agassiz Mountain Institution, British Columbia. *Canadian Geotechnical Journal, 21(3):505-517.*
- Mathewes, R.W. 1990. Debris flows, paleolimnology, and native oral history: A case history from British Columbia. Poster, AMQUA-CANQUA Conference, University of Waterloo, Waterloo, ON.
- McPherson, H.J. and Hirst, F. 1972. Sediment changes on two alluvial fans in the Canadian Rocky Mountains. *In Mountain Geomorphology: Processes in the Canadian Cordillera.* O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd, Vancouver, BC, p161-176.
- Menzies, J. and Kamil Z. In prep. Microstructures within a modern debris flow deposit derived from a Quaternary glacial diamicton - a comparative micromorphological study. Brock University, Departments of Geography and Earth Sciences, St. Catherines, ON.
- Miles, M.J. and Kellerhals, R. 1981. Some engineering aspects of debris torrents. *In Proceedings, 5th Canadian Hydrotechnical Conference, Fredericton NB, Canadian Society of Civil Engineers.*
- Miles, M.J., Kellerhals R. and A.H. Rice. 1992. Performance of buried fiber optic telecommunications cable subjected to debris torrent events Coquihalla Corridor, British Columbia. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p339-346.*
- Millard, T.H. 1993. Sediment in forested and logged gullies, coastal British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Millard, T.H. 1999. Debris flow initiation in coastal British Columbia gullies. British Columbia Ministry of Forests, Vancouver Forest Region, Nanaimo, BC, Technical Report, TR-002, 22p.
- Millard, T.H, Wise, M.P., Rollerson, T.R., Chatwin, S. and Hogan, D. 1998. Gully system hazards, risks, and forestry operations in coastal British Columbia. *In Proceedings, 8th Congress of the International Association of Engineering Geology, Vancouver, BC, D Moore and O. Hungr (editors), Balkema Press, p1149-1156.*
- Monger, J.W.H. (editor) 1994. Geology and geological hazards of the Vancouver region, southwestern British Columbia. Geological Survey of Canada, Bulletin 481.

- Moore, D.P. and Mathews, W.H. 1978. The Rubble Creek landslide, southwestern British Columbia. *Canadian Journal of Earth Sciences*, 15:1039-1052.
- Morgan, G.C., Rawlings, G.E. and Sobkowicz, J.C. 1992. Evaluating total risk to communities from large debris flows. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p225-236.*
- Murray, D.N., Currie, M.V., Skermer, N.A. and Henry, W.K. 1998. Design and construction of the Upper Mackay Creek debris basin in North Vancouver District. *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC.*
- Nasmith, H.W. and Mercer, A.G. 1979. Design of dykes to protect against debris flows at Port Alice, British Columbia. *Canadian Geotechnical Journal*, 16(4):748-757.
- Oden, M.E. 1994. Debris recharge rates in tormented gullies on the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- O'Loughlin, C.L. 1972. Investigation of the stability of the steepland forest soils in the Coast Mountains, southwest British Columbia. Ph.D. thesis, University of British Columbia, Department of Geography, Vancouver, BC, 147p.
- O'Loughlin, C.L. 1972. A preliminary study of landslides in the Coast Mountains of southwestern British Columbia. *In Mountain Geomorphology: Processes in the Canadian Cordillera.* O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd., Vancouver, BC, p101-112.
- Owens, I.F. 1972. Morphological characteristics of alpine mudflows in the Nigel Pass area. *In Mountain Geomorphology: Processes in the Canadian Cordillera.* O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd., Vancouver, BC, p93-100.
- Owens, I.F. 1973. Alpine mudflows in the Nigel Pass area, Canadian Rocky Mountains. PhD thesis, University of Toronto, Department of Geography, Toronto, ON, 218p.
- Owens, P. and Slaymaker, O. 1992. Late Holocene sediment yields in small and subalpine drainage basins, British Columbia. *In Erosion, Debris Flows and Environment in Mountain Regions.* D.E. Walling, T.R. Davies and B. Hasholt (editors). International Association of Hydrological Sciences Publication 209, p147-154.
- Patton, F.D. 1976. The Devastation Glacier slide, Pemberton, B.C. Abstract *In Symposium on Geomorphology of the Canadian Cordillera and its Bearing on the Mineral Deposits.* Geological Association of Canada, Cordilleran Section, p26.
- Piteau Associates Ltd. 1993. Mount Goslin debris torrent hazard study, Tete Jaune Cache. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch.*
- Podor, A.P. 1992. Recent debris flow frequency and magnitude at West Wilson Creek, Banff National Park, Alberta. Masters thesis, University of Waterloo, Waterloo, ON, 221p.
- Price, J. 1986. Debris torrent control facilities, Vancouver, BC, Canada. *IABSE Periodica* 3/1986, IABSE Structures C-38/86, p60-61.
- Radomske, E. 1999. Hazard mitigation after the fact: the June 1990 debris flow accident on Philpott Road, Okanagan Valley. *In Program and Abstracts, 42nd Annual Meeting of the Western Division of the Canadian Association of Geographers, Okanagan University College, Kelowna, BC.*
- Readshaw, E.E. 1968. Camp Creek slide. Internal report. British Columbia Ministry of Highways, Victoria, BC.*

- Rollerson, T.P., Millard, T.P. and Thomson, B. 1997. Bridal Creek area preliminary terrain hazard reconnaissance 1997. Report to BC Ministry of Forests, Chilliwack Forest District, 13p.*
- Rollerson, T.R., Thomson, B. and Millard, T.H. 1997. Identification of coastal British Columbia terrain susceptible to debris flows. *In* Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p484-495.
- Rood, K.M. 1984. An aerial photograph inventory of frequency and yield of mass wasting on the Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Land Management Report 34, Victoria BC.
- Rood, K.M. 1990. Site characteristics and landsliding in forested and clearcut terrain, Queen Charlotte Islands, BC. British Columbia Ministry of Forests, Land Management Report 64, Victoria, BC, 46p.
- Russell, S.O.D. 1972. Behaviour of steep creeks in a large flood. *In* Mountain Geomorphology: Processes in the Canadian Cordillera. O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd, Vancouver, BC, p223-227.
- Russell, S.O.D. 1990. Debris torrents and professional responsibilities. American Society of Civil Engineers, Journal of Professional Activities, Jan 1990.
- Ryder, J.M. 1971. The stratigraphy and morphology of para-glacial alluvial fans in south-central British Columbia. Canadian Journal of Earth Science, 8:279-298.
- Ryder, J.M. 1971. Some aspects of the morphology of paraglacial alluvial fans in south central British Columbia. Canadian Journal of Earth Sciences, 8:1252-1264.
- Ryder, J.M. 1998. Geomorphological processes in alpine areas of Canada: the effects of climate change and their impacts on human activities. Geological Survey of Canada, Bulletin 524, 44p.
- Saczuk, E.A.R. 1996. Mapping geomorphic hazard sites using GIS between Bow Pass and Seebe in southwestern Alberta. Honours thesis, University of Manitoba, Winnipeg, MB, p56.
- Saczuk, E.A.R. 1998. GIS-based modelling of debris flows in Banff National Park, Alberta. Masters thesis, University of Manitoba, Winnipeg, MB, 101p.
- Saczuk, E.A.R. and Campbell, M. In prep. Tool for the estimation of volume of debris in debris flow channels.
- Saczuk, E.A.R. and Gardner, J.S. 1998. GIS-based mapping and modelling of debris flows in Banff National Park. Canadian Journal of Remote Sensing, 24(1):53-59.
- Sauchyn, M.A. 1983. Evaluation of botanical methods for dating debris flow deposits and estimating debris flow hazard in the Canadian Rocky Mountains. Masters thesis, University of Waterloo, Waterloo, ON, 147p.
- Sauchyn, M.A. 1984. Open rock basins and debris fans in the Kananaskis area, southern Canadian Rocky Mountains. Unpublished Ph.D. dissertation. University of Waterloo, Waterloo, ON.
- Sauchyn, M.A., Gardner, J.S. and Suffling, R. 1983. Evaluation of botanical methods of dating debris flows and debris flow hazard in the Canadian Rocky Mountains. Physical Geography, 2:182-201.
- Sauder, E.A., Krag, R.K. and Wellburn, G.V. 1987. Logging and mass wasting in the Pacific Northwest with application to the Queen Charlotte Islands, BC: a literature review. British Columbia Ministry of Forests, Land Management Report 53, Victoria, BC, 26p.
- Schwab, J.W. 1983. Mass wasting: October-November 1978 storm, Rennell Sound, Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Research Note 91, Victoria BC.

- Schwab, J.W. 1997. Historical debris flows, British Columbia north coast. *In Proceedings, Forestry Geotechnique and Resource Engineering, 11th Vancouver Geotechnical Society Symposium, Richmond BC.*
- Schwab, J.W. 1998. Landslides on the Queen Charlotte Islands: processes, rates and climatic events. *In Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions.* D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Schwab, J.W. 1998. Debris avalanches-flows on British Columbia's north coast. *In Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions.* D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Septer, D. and Schwab, J.W. 1995. Rainstorm and flood damage: northwest British Columbia 1891-1991. British Columbia Ministry of Forests, Land Management Handbook 31, Victoria BC.
- Sharp, R.P. 1942. Mudflow levees. *Journal of Geomorphology*, 5:222-227.
- Skерmer, N.A. 1984. M Creek debris flow disaster. *In Proceedings, Canadian Geotechnical Conference, Canadian Case Histories of Landslides, Toronto, ON, p187-194.*
- Skерmer, N.A. 1985. The control of debris flows. *In Proceedings, 81st Annual Meeting of the Geological Society of America, Cordillera Section, Vancouver, BC, p408-425.*
- Skерmer, N. 1993. Landslides in the mountains. *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC, p85-90.*
- Skерmer, N. and Russell, D. 1988. 28th of October (a day of coincidence for floods on Howe Sound). *BC Professional Engineer, Vancouver, BC, May 1988, p21-23.*
- Slaymaker, O. 1988. Slope erosion and mass movement in relation to weathering in geochemical cycles. *In Physical and Chemical Weathering in Geochemical Cycles.* A Lerman and M. Meybeck (editors). Kluwer Academic, Rotterdam, p83-111.
- Slaymaker, O. 1988. The distinctive attributes of debris torrents. *Hydrological Sciences Journal*, 33(6):567-573.
- Slaymaker, O. 1990. Climate change and erosion processes in mountain regions of western Canada. *Mountain Research and Development*, 10:171-182.
- Slaymaker, O. 1990. Debris torrent hazard in eastern Fraser and Coquihalla valleys. *Western Geography*. 1(1):34-48.
- Slaymaker, O. 1990. Natural hazards in mountain terrain: Howe Sound, British Columbia. *Field Tour, Canadian Association of Geographers, Western Division Annual Meeting, University of British Columbia, Vancouver, BC, 53p.*
- Slaymaker, O. 1993. The sediment budget of the Lillooet River basin. *Physical Geography*, 14:304-320.
- Slaymaker, O. 1999. Natural hazards in British Columbia: an interdisciplinary and inter-institutional challenge. *International Journal of Earth Sciences*, 88:317-324.
- Slaymaker, O. 1999. Regional controls on debris flows in British Columbia. *In Proceedings, 2nd National Taiwanese Debris Flow Conference, Hualien, Taiwan.*
- Slaymaker, O. *In press.* Assessment of the geomorphic impacts of forestry in British Columbia. *Ambio.*
- Slaymaker, O. and McPherson, H.J. (editors). 1972. *Mountain Geomorphology: Processes in the Canadian Cordillera.* BC Geographical Series 14, Tantalus Research Ltd., Vancouver, BC, 274p.

- Slaymaker, O. and McPherson, H.J., 1977. An overview of geomorphic processes in the Canadian Cordillera. *Zeitschrift für Geomorphologie*, 21:169-186.
- Slaymaker, O., Hungr, O., Desloges, J., Lister, D.R., Miles, M.J. and VanDine, D.F. 1987. Debris torrent and debris flood hazards, Lower Fraser, Nicolum and Coquihalla valleys, BC. Excursion B2. International Association of Hydrological Sciences Symposium on Forest Hydrology and Watershed Management, 70 p.
- Smith, H.R. and Patton, F.D. 1984. Comparison of the Devastation Glacier Slide with other high velocity debris flows. *In Proceedings, 4th International Symposium on Landslides*, Toronto, ON, Abstracts, p96.
- Sobkowicz, J.C., Hungr, O. and Morgan, G.C. 1995. Probabilistic mapping of a debris flow hazard area. *In Proceedings, 48th Canadian Geotechnical Conference*, Vancouver, BC. Canadian Geotechnical Society, p519-529.
- Sterling, S.M. 1997. Influence of bedrock type on the magnitude, frequency and spatial distribution of debris torrents on northern Vancouver Island, BC. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC, 117 p.
- [[Strilaeff, P.W. 1984. Debris torrent alert system for Alberta Creek at Lions Bay, BC *Professional Engineer*, v35(2):14-16.]]
- Terratech Consulting Ltd. 1999. Detailed terrain stability mapping (TSIL C) Hummingbird Creek and Mara Creek watersheds. Map and Report to Riverside Forest Products Ltd.*
- Thomson, B. 1983. Terrain features and geological processes maps and legends for the Goat-Milk River Project Area (NTS 93H/7). British Columbia Ministry of Environment, Victoria, BC.
- Thomson, B. 1986. Potential introduced rapid mass movement debris rating map : Smokey Creek-Falls Creek. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheets 82F.043 and 82F.053).
- Thomson, B. 1987. Chapman Creek landslide inventory. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend.
- Thomson, B. 1989. Pemberton Creek: potential clearcut landslide and stream impact rating. Ministry of Environment Lands and Parks, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheet 92J.036).
- Thurber Consultants Ltd./Ker Priestman & Associates Ltd. 1986. Harvey and Magnesia Creek debris-torrent structures. *Canadian Consulting Engineer*, September / October 1986, p51-52.
- Thurber Consultants Ltd./Ker Priestman & Associates Ltd. No date. Site visit to debris torrent facilities at Charles Creek, Harvey Creek, Magnesia Creek, Alberta Creek, Lions Bay, BC. Field Guide.
- Thurber Consultants. Ltd. 1976. Port Alice Rumble Beach debris flow. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Thurber Consultants Ltd. 1977. Fitzsimmons Creek, Whistler, British Columbia, geotechnical review of landslides and debris flows. Report to British Columbia Ministry of Environment, Land Management Branch, Victoria, BC, 8p.*
- Thurber Consultants Ltd. 1983. Debris torrents and flooding hazards, Highway 99, Howe Sound. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 24p plus appendices.*
- Thurber Consultants Ltd. 1983. Rogers Pass. Volume 2. Hydrology and debris flow potential. Report to CP Rail Special Projects, Calgary, AB.*
- Thurber Consultants Ltd. 1984. Debris torrents, a review of mitigative measures. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 32p plus appendices.*

- Thurber Consultants Ltd. 1984. Schlufield Creek debris torrent, December 14, 1984. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Thurber Consultants Ltd. 1985. Cathedral Mountain debris flow, Report to CP Rail Special projects, Calgary AB, 37p.*
- Thurber Consultants Ltd. 1985. Debris torrent assessment, Wahleach and Floods, Highway 1, Hope to Boston Bar Summit, Coquihalla Highway. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 27p plus appendices.*
- Thurber Consultants Ltd. 1987. Debris torrent hazards along Highway 1, Sicamous to Revelstoke. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 20p plus appendices.*
- Thurber Engineering Ltd and Golder Associates Ltd. 1992. Cheekeye River terrain hazard study. Report to British Columbia Ministry of Environment, Lands and Parks, Victoria, BC.*
- Tripp, D. 1986. Using large organic debris to restore fish habitat in debris-torrented streams. British Columbia Ministry of Forests and Lands, Land Management Report 47, 26p.
- Tse, C.M., Chu, T., Wu, R., Hungr, O. and Li, F.H. 1999. A risk-based approach to landslide hazard mitigation design. *In* Proceedings, Hong Kong Institution of Engineers, Geotechnical Division Annual Seminar, Hong Kong, p35-42.
- VanDine Geological Engineering. 1986. Development of awareness, knowledge and mitigation of debris torrents in British Columbia. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 31p.*
- VanDine Geological Engineering. 1990. Geological engineering assessment of the Ottawa Hill (Slocan Valley) debris torrents of May 1990. Report to British Columbia Ministry of Forests, Arrow Forest District, 16p plus appendices.*
- VanDine Geological Engineering. 1991. Kennedy Lake 1991 slope failures. Report to Fletcher Challenge Canada and MacMillan Bloedel Limited, Nanaimo, BC, 22p plus appendices.*
- VanDine Geological Engineering. 1992. Design of mitigative works for Boat Launch Creek, Kennedy Lake, BC. Report to British Columbia Ministry of Forests, Port Alberni District, Port Alberni, BC, 16p.*
- VanDine Geological Engineering Limited. 1998. Assessment of debris flow potential of Newman Creek, Howe Sound. Report to British Columbia Ministry of Transportation and Highways, South Coast Region, Burnaby, BC, 11p.*
- VanDine Geological Engineering Limited. 1999. Reconnaissance of M (Yahoo) Creek. Report to BC Rail, North Vancouver, BC, 6p.*
- VanDine, D.F. 1985. Debris flows and debris torrents in the Southern Canadian Cordillera. *Canadian Geotechnical Journal*, 22(1):44-68.
- VanDine, D.F. 1985. Debris flows and debris torrents in the Southern Canadian Cordillera: reply. *Canadian Geotechnical Journal*. 22(4):608-609.
- VanDine, D.F. 1992. Low magnitude - high frequency mass movements. *In* Proceedings, Workshop on Geologic Hazards in British Columbia, Victoria, BC. British Columbia Geological Survey Branch Open File 1992-15, p99-107.
- VanDine, D.F. 1996. Debris flow control structures for forest engineering. British Columbia Ministry of Forests Working Paper 22/1996, Victoria, BC, 75p.
- VanDine, D.F. and Lister, D.R.. 1983. Debris torrents - a new natural hazard?. *BC Professional Engineer*, Vancouver, BC, December, p9-11.
- VanDine, D.F., Hungr, O., Lister, D.R., and Chatwin, S.C. 1997. Channelized debris flow mitigation structures in British Columbia. *In* Proceedings, 1st International Conference on

- Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p605-615.
- VanDine, D.F., Jordan, P. and Boyer, D. 1999. Perry Ridge, an example of a risk assessment for forestry planning. *In Proceedings, Confronting Uncertainty: Managing Change in Water Resources and the Environment*, Richmond, BC. Canadian Water Resources Association, BC Chapter, Vancouver, BC, p255-262.
- Ward, B.C., Jackson, L.E. and Savigny, K.W. 1992. Evolution of Surprise Rapids landslide, Yukon Territory. Geological Survey of Canada, Paper 90-18, 25p.
- Ward, P.R.B., Skermer, N.A. and LaCas, B.D. 1991. The 50-year flood on Fitzsimmons Creek, Whistler, British Columbia. BC Professional Engineer, Vancouver, BC, December 1991, p5-6.
- Wilford, D.J. and Schwab, J.W. 1982. Soil mass movements in the Rennell Sound area, Queen Charlotte Islands, British Columbia. *In Proceedings, Symposium of Canadian Hydrology*, Fredericton, NB, 21 p.
- Wilford, D.J. and Sidle, R.C. 1999. Forestry on fans: linking geomorphic processes to site prescriptions. 1999. In Abstracts, Fall Meeting of the American Geophysical Union, San Francisco, CA.
- Wilkinson, J.M.T., 1996. Landslide initiation: a unified geostatistical and probabilistic modelling technique for terrain stability assessment. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.
- Wilkinson, J.M.T. and Fannin, R.J. 1997. A probabilistic technique for terrain stability assessment of open slopes in coastal BC. *In Proceedings, 11th Annual Vancouver Geotechnical Society Symposium*, Vancouver, BC, p17-30.
- Winder, C.G. 1965. Alluvial cone construction by alpine mudflow in a humid temperate region. *Canadian Journal of Earth Sciences*, 2:270-277.
- Wise, M.P. 1996. Debris flow control structure Escalante River WRP. *In Proceedings, Coastal Forest Site Rehabilitation Workshop*, BC Forestry Continuing Studies Network, Nanaimo, BC.
- Wise, M.P. 1997. Probabilistic modelling of debris flow travel distance using empirical volumetric relationships. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.
- Woods, P.J. 1984 A debris flow landslide at Port Moody. *In Proceedings, 37th Canadian Geotechnical Conference*, Toronto, ON, p217-222.
- Young, S.E. 1992. Analysis of slope failure and logging relationships in the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.

Section B Single debris flow/creek studies/reports

- Bartle, H.T., Rollerson, T.P. and Thomson, B. 1997. Report on the May 31, 1997 Gowan Creek debris flow and fatality. Report to British Columbia Ministry of Forests, Squamish Forest District, 13 p.*
- Bovis, M.J. and Jakob, M. In press. The July 30, 1998 debris flow and landslide dam at Capricorn Creek, Mount Meager Volcanic Complex, British Columbia. *Canadian Journal of Earth Sciences*.
- Broscoe, A.J. and Thomson, S. 1969. Observations on an alpine mudflow, Steele Creek, Yukon. *Canadian Journal of Earth Science*, 6:219-229.
- Cass, D.E., Kenning, B.F.I. and Rawlings, G. 1992 The Philpott Road debris failures – Kelowna, BC, 1990. the impacts of geology, hydrology and logging activities. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p319-330.*
- Church, M. and Russell, S.O.D. 1983. Recent history and condition of Alberta Creek at Lions Bay, British Columbia: implications for the safety of settlement at Lions Bay. University of British Columbia, Vancouver, BC. Internal report.
- Clague, J.J., Evans, S.G. and Blown, I.G. 1985. A debris flow triggered by the breaching of a moraine-dammed lake, Klattasine Creek, British Columbia. *Canadian Journal of Earth Sciences*, 22(10):1492-1502.
- Couture, R. and Evans, S.G. 2000. Five-Mile Creek debris flow, Banff National Park, near Banff, Alberta, August 4th, 1999. Geological Survey of Canada, Open File 3876.
- Couture, R. and Evans, S.G. 2000. The East Gate landslide, Beaver Valley, Glacier National Park, Columbia Mountains, British Columbia. Geological Survey of Canada, Open File 3877.
- Cruden, D.M. and Lu, Z.Y. 1989. The geomorphic impact of the catastrophic October 1984 flood, on the platform of the Spanish River, southwest British Columbia. *Canadian Journal of Earth Sciences*, 26:336.
- Cruden, D.M. and Lu, Z.Y. 1992. The rockslide and debris flow from Mount Cayley, BC, in June 1984. *Canadian Geotechnical Journal*, 29(4):614-626.
- Currie, M.V., Skermer, N.A., and West-Sells, R.J. 1996. Debris flow hazard mitigation at Upper Mackay Creek, North Vancouver. *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC.*
- Dumoulin, J. 1965. Her Majesty the Queen vs. Canadian Pacific Railway Company, Twin Butte mudslide judgement. Exchequer Court of Canada, Victoria, BC, 29p.
- EBA Engineering Consultants Ltd. 1998. Hillside industrial park debris flow, debris flood and landslide hazard assessment, Port Mellon, BC. Report to Sunshine Coast Regional District.*
- EBA Engineering Consultants Ltd. 1998. History of debris floods on Susap Creek fan, lower Similkameen Valley. Report to Canada Department of Indian and Northern Affairs, Vancouver, BC.*
- EBA Engineering Consultants Ltd. 1999. Clementine Creek debris flow investigation. Report to Burrard Yacht Club, Vancouver, BC.*
- EBA Engineering Consultants Ltd. 2000. Deroche Creek debris flow and debris flood study. Report to Fraser Valley Regional District.*
- Evans, S.G., Hungr, O. and Clague, J.J. In press. The 1984 rock avalanche from the western flank of Mt. Cayley, British Columbia: description and dynamic analysis of a hyper-mobile landslide. *Engineering Geology*.
- Eyles, N. and Clague, J.J. 1987. Landsliding caused by Pleistocene glacial lake ponding - an example from central British Columbia. *Canadian Geotechnical Journal*, 24(4):656-663.

- Fannin, R.J. and Wilkinson, J.M.T. 1995. An analysis of the Jaminson Creek landslide. *In* Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p635-642.
- Friele, P.A., Ekes, C. and Hickin, E.J. 1999. Evolution of Cheekeye fan, Squamish, British Columbia: Holocene sedimentation and implications for hazard assessment. *Canadian Journal of Earth Sciences*, 36:2023-2031.
- Golder Associates Ltd. 1962. Landslide on Canadian Pacific Railway at Twin Butte, British Columbia. Report to Canadian Wheat Board.*
- Golder Associates Ltd. 1990. Debris torrent hazard assessment kilometre 1020, Floods, BC. Report to Trans-Mountain Pipeline Company Ltd, Vancouver, BC.*
- Golder Associates Ltd. 1990. Philpott Road potential for slides and debris flows, Kelowna. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Hardy, R.M., Morgenstern, N.R. and Patton, F.D. 1978. Report of the Garibaldi Advisory Panel. Report to the Deputy Minister, British Columbia Department of Highways.
- Harris, S.A. and McDermid, G. 1998. Frequency of debris flows on the Sheep Mountain fan, Klauane Lake, Yukon Territory. *Zeitschrift fur Geomorphologie*, 42(2):159-175.
- Hungr, O. and Evans, S.G. 1984. An example of a peat flow near Prince Rupert, British Columbia. *Canadian Geotechnical Journal*, 22:246-249.
- Jackson, Jr., L.E. 1979. A catastrophic glacial outburst flood (jokulhlaup) mechanism for debris flow generation at the Spiral Tunnels, Kicking Horse River basin, British Columbia. *Canadian Geotechnical Journal*, 16(4):806-813.
- Jackson, Jr., L.E. 1979. Mystery flood solved: CPR records revealed the 1978 catastrophe was not unique. *Geos*, 8(3):2-4.
- Jackson, Jr., L.E. 1980. New evidence in the origin of the September 6, 1978 jokulhlaup from the Cathedral Glacier. *Geological Survey of Canada, Paper 80-1B*, p292-294.
- Jackson, Jr., L.E., Hungr, O., Gardner, J.S. and MacKay, C. 1989. Cathedral mountain debris flows, Canada. *Bulletin International Association of Engineering Geology*, 40:35-54.
- Jakob, M., Hungr, O. and Thomson, B. 1997. Two debris flows with anomalously high magnitude. *In* Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p382-394.
- Jakob, M., Hungr, O., Anderson, D., Fuller, T. and Ayotte, D. In press. The July 7, 1997 debris flow at Hummingbird Creek. *Canadian Geotechnical Journal*.
- Jakob, M., Martin, S., Skermer, N., Campbell, C., Anderson, D. and Fuller, T. 1998. A record breaking debris flow at Hummingbird Creek, Mara Lake, BC. *In* Proceedings 8th Congress International Association of Engineering Geology and the Environment, Vancouver, BC. D. Moore and O. Hungr (editors), p2091-2098.
- Jones, W.C. 1959. Cheekeye River mudflows. British Columbia Department of Mines, Victoria, BC, memorandum, 9p.*
- Lister, D.R. 1988. Slokan Lake (north end) potential debris flow. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lister, D.R. 1991. Debris torrent 33km north of Sayward. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lu, Z.Y. and Cruden, D.M. 1996. Two debris flow modes on Mount Cayley, British Columbia. *Canadian Geotechnical Journal*, 32(1):123-139.

- Moore, D.P. and Mathews, W.H. 1978. The Rubble Creek landslide, southwestern British Columbia. *Canadian Journal of Earth Sciences*, 15:1039-1052.
- Patton, F.D. 1976. The Devastation Glacier slide, Pemberton, B.C. Abstract *In* Symposium on Geomorphology of the Canadian Cordillera and its Bearing on the Mineral Deposits. Geological Association of Canada, Cordilleran Section, p26.
- Piteau Associates Ltd. 1993. Mount Goslin debris torrent hazard study, Tete Jaune Cache. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch.*
- Podor, A.P. 1992. Recent debris flow frequency and magnitude at West Wilson Creek, Banff National Park, Alberta. Masters thesis, University of Waterloo, Waterloo, ON, 221p.
- Readshaw, E.E. 1968. Camp Creek slide. Internal report. British Columbia Ministry of Highways, Victoria, BC.
- Skermer, N. and Russell, D. 1988. 28th of October (a day of coincidence for floods on Howe Sound). *BC Professional Engineer*, Vancouver, BC, May 1988, p21-23.
- Skermer, N.A. 1984. M Creek debris flow disaster. *In* Proceedings, Canadian Geotechnical Conference, Canadian Case Histories of Landslides, p187-194.
- Smith, H.R. and Patton, F.D. 1984. Comparison of the Devastation Glacier Slide with other high velocity debris flows. *In* Proceedings, 4th International Symposium on Landslides, Toronto, ON, Abstracts, p96.
- Terratech Consulting Ltd. 1999. Detailed terrain stability mapping (TSIL C) Hummingbird Creek and Mara Creek watersheds. Map and Report to Riverside Forest Products Ltd.
- Thurber Consultants Ltd. 1977. Fitzsimmons Creek, Whistler, British Columbia, geotechnical review of landslides and debris flows. Report to British Columbia Ministry of Environment, Land Management Branch, Victoria, BC, 8p.*
- Thurber Consultants Ltd. 1984. Schlufield Creek debris torrent, December 14, 1984. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Thurber Consultants Ltd. 1985. Cathedral Mountain debris flow, Report to CP Rail Special projects, Calgary Alberta, 37p.
- Thurber Consultants. Ltd. 1976. Port Alice Rumble Beach debris flow. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Thurber Engineering Ltd and Golder Associates Ltd. 1992. Cheekeye River terrain hazard study. Report to British Columbia Ministry of Environment, Lands and Parks, Victoria, BC.
- VanDine Geological Engineering Limited. 1998. Assessment of debris flow potential of Newman Creek, Howe Sound. Report to British Columbia Ministry of Transportation and Highways, South Coast Region, Burnaby, BC, 11p.
- VanDine Geological Engineering Limited. 1999. Reconnaissance of M (Yahoo) Creek. Report to BC Rail, North Vancouver, BC, 6p.
- VanDine Geological Engineering. 1990. Geological engineering assessment of the Ottawa Hill (Slocan Valley) debris torrents of May 1990. Report to British Columbia Ministry of Forests, Arrow Forest District, Castlegar, BC, 16p plus appendices.
- VanDine Geological Engineering. 1991. Kennedy Lake 1991 slope failures. Report to Fletcher Challenge Canada and MacMillan Bloedel Limited, Nanaimo, BC, 22p plus appendices.
- Ward, P.R.B., Skermer, N.A. and LaCas, B.D. 1991. The 50-year flood on Fitzsimmons Creek, Whistler, British Columbia. *BC Professional Engineer*, Vancouver, BC, December 1991, p5-6.
- Woods, P.J. 1984 A debris flow landslide at Port Moody. *In* Proceedings, 37th Canadian Geotechnical Conference, Toronto, ON, p217-222.

Section C Regional studies/reports

- Brardinoni, F. In prep. The frequency distribution of small debris flows in the Capilano River basin. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Carr, K. 1989. Debris flow hazard in the Cathedral Mountain area, Kicking Horse Pass, British Columbia: causes, effects and response to the risk. Undergraduate paper, Wilfred Laurier University, Department of Earth Sciences, Waterloo, ON, 32p.
- Church, M. and Desloges, J.R. 1984. Debris torrents and natural hazards of steep mountain channels: east shore of Howe Sound: University of British Columbia, Department of Geography, Vancouver, BC, 83p.
- Cruden, D.M. and Lu, Z.Y. 1989. The geomorphic impact of the catastrophic October 1984 flood, on the platform of the Spanish River, southwest British Columbia. *Canadian Journal of Earth Sciences*, 26:336.
- Currie, M.V., Skermer, N., Jakob, M. and West-Sells, B. 1999. Debris flow hazards in North Vancouver District: how do we manage the risk? *In Proceedings, Confronting Uncertainty: Managing Change in Water Resources and the Environment*, Richmond, BC. Canadian Water Resources Association, BC Chapter, p12-14.
- Dagg, B.R. 1987. Debris supply torrent-prone channels on the east side of Howe Sound, British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- EBA Engineering Consultants Ltd. 1996. Debris flow initiation potential, gully assessment procedures, and meteorological conditions associated with debris flows in the Kalum Forest District, northwestern British Columbia. Report to Ministry of Forests, Prince Rupert Region, 32p.*
- Eisbacher, G.H. 1982. Howe Sound debris flows. *Geoscience Canada*, 9(2):132.
- Evans, S.G. and Lister, D.R. 1984. The geomorphological effects of the July 1983 rainstorms in the southern Cordillera and their impact on transportation facilities. *Geological Survey of Canada, Paper 84-1B*, p223-235.
- Eyles, N. 1987. Late Pleistocene debris-flow deposits in large glacial lakes in British Columbia and Alaska. *Sedimentary Geology*, 53(1-2):33-71.
- Gardner, J.S. 1981. Ephemeral and episodic transport of debris on mountain slopes. Progress Report on Research Conducted Under Permit from Parks Canada, Western Region Parks Canada, Calgary, AB, 22p.
- Gardner, J.S. 1986. Sediment movement in ephemeral streams on mountain slopes, Canadian Rocky Mountains. *In Proceedings, Hillslope Processes, Binghamton Symposia in Geomorphology*. A.D. Abraham, editor. International Series 16, Allen & Unwin Inc, Winchester, p97-113.
- Gottesfeld, A.S., Mathewes, R.W., Johnson, and Gottesfeld, L.M. 1991. Holocene debris flows and environmental history, Hazelton area, British Columbia. *Canadian Journal of Earth Sciences*, 28(10):1583-1593.
- Gustafson, C.A. 1985. Debris flows along the Slims River valley, Kluane National Park, Yukon Territory. Masters thesis, University of Calgary, Calgary, AB.
- Harris, S.A. and Gustafson, C.A. 1993. Debris flow characteristics in an area of continuous permafrost, St. Elias Range, Yukon Territory. *Zeitschrift fur Geomorphologie*, 37(1):41-56.
- Hawley, P.M. 1989. Identification, evaluation and mitigation of debris flow hazards in British Columbia. *In Proceedings, Conference XX, International Erosion Control Association*, Vancouver, BC, p471.

- Hogan, D.L. 1986. Channel morphology of unlogged, logged, and debris torrented streams in the Queen Charlotte Islands. British Columbia Ministry of Forests and Lands, Land Management Report 49, Victoria, BC, 94p.
- Hogan, D.L. and J.W. Schwab. 1991. Meteorological conditions associated with hillslope failures on the Queen Charlotte Islands. British Columbia Ministry of Forest, Land Management Report 73, Victoria, BC.
- Jackson, Jr., L.E. 1987. Debris flow hazard in the Canadian Rocky Mountains, Geological Survey of Canada, Paper 86-11, 10p.
- Jacob, N. 2000. Debris flow activity in a forest environment, Gaspésie, Québec: triggering, frequency and magnitude. Masters thesis, Université Laval, Department of Geography (Centres d'Études Nordiques), Laval QU, 96p.
- Jordan, P. 1990. Large debris flows in the Meager Creek volcanic complex, British Columbia. *Eos*, 71:1145. (Paper presented at American Geophysical Union, Pacific Northwest regional meeting, Seattle.)
- Jordan, R.P. 1995. Debris flows in the southern Coast Mountains, British Columbia: dynamic behaviour and physical properties. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Kerr Wood Liedal Ltd./EBA Engineering Consultants Ltd. 1999. Overview report on debris flow hazards. Report to District of North Vancouver, BC.
- Klohn Leonoff Limited. 1994. Flood hazard management plan. Report to the Regional District of Squamish, BC.
- Klohn-Crippen Consultants Ltd. 1998. Terrain stability inventory - alluvial and debris torrent fans, Kootenay Region. Report to British Columbia Ministry of Environment Lands and Parks, Kootenay Region.
- Krag, R.K., Sauder, E. A. and Welburn, G.V. 1986. A forest engineering analysis of landslides in logged areas on the Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Land Management Report 43, Victoria BC, 138p.
- Lister, D.R. 1983. Chilliwack to Hope debris torrents, near Wahleach. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lister, D.R., Morgan, G.C., VanDine, D.F. and Kerr, J.G.W. 1984. Debris torrents in Howe Sound, British Columbia. *In* Proceedings, 4th International Symposium on Landslides, Toronto ON, p649-654.
- Lu, Z.Y. 1992. Prehistoric debris avalanches from Mount Cayley volcano, British Columbia: discussion. *Canadian Journal of Earth Sciences*, 29:1342-1343.
- Mathewes, R.W. 1990. Debris flows, paleolimnology, and native oral history: A case history from British Columbia. Poster, AMQUA-CANQUA Conference, University of Waterloo, Waterloo, ON.
- Miles, M.J., Kellerhals R. and A.H. Rice. 1992. Performance of buried fiber optic telecommunications cable subjected to debris torrent events Coquihalla Corridor, British Columbia. *In* Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p339-346.
- Millard, T. 1999. Debris flow initiation in coastal British Columbia gullies. British Columbia Ministry of Forests, Vancouver Forest Region, Technical Report, TR-002, 22p.
- Owens, I.F. 1973. Alpine mudflows in the Nigel Pass area, Canadian Rocky Mountains. PhD thesis, University of Toronto, Department of Geography, Toronto, ON, 218p.

- Owens, P. and Slaymaker, O. 1992. Late Holocene sediment yields in small and subalpine drainage basins, British Columbia. *In* Erosion, Debris Flows and Environment in Mountain Regions. D.E. Walling, T.R. Davies and B. Hasholt (editors). International Association of Hydrological Sciences Publication 209, p147-154.
- Rollerson, T.P., Millard, T.P. and Thomson, B. 1997. Bridal Creek area preliminary terrain hazard reconnaissance 1997. Report to BC Ministry of Forests, Chilliwack Forest District, 13p.*
- Russell, S.O.D. 1972. Behaviour of steep creeks in a large flood. *In* Mountain Geomorphology: Processes in the Canadian Cordillera. O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd, Vancouver, BC, p223-227.
- Sauchyn, D. 1984. Open rock basins and debris fans in the Kananaskis area, southern Canadian Rocky Mountains. Unpublished Ph.D. dissertation. University of Waterloo, Waterloo, ON.
- Schwab, J.W. 1983. Mass wasting: October-November 1978 storm, Rennell Sound, Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Research Note 91, Victoria BC.
- Schwab, J.W. 1997. Historical debris flows, British Columbia north coast. *In* Proceedings, Forestry Geotechnique and Resource Engineering, 11th Vancouver Geotechnical Society Symposium, Richmond BC.
- Schwab, J.W. 1998. Debris avalanches-flows on British Columbia's north coast. *In* Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions. D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Septer, D. and Schwab, J.W. 1995. Rainstorm and flood damage: northwest British Columbia 1891-1991. British Columbia Ministry of Forests, Land Management Handbook 31, Victoria BC.
- Slaymaker, O. 1990. Debris torrent hazard in eastern Fraser and Coquihalla valleys. *Western Geography*. 1(1):34-48.
- Slaymaker, O. 1999. Regional controls on debris flows in British Columbia. *In* Proceedings, 2nd National Taiwanese Debris Flow Conference, Hualien, Taiwan.
- Sterling, S.M. 1997. Influence of bedrock type on the magnitude, frequency and spatial distribution of debris torrents on northern Vancouver Island, BC. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC, 117 p.
- Thomson, B. 1986. Potential introduced rapid mass movement debris rating map : Smokey Creek-Falls Creek. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheets 82F.043 and 82F.053).*
- Thurber Consultants Ltd. 1983. Debris torrents and flooding hazards, Highway 99, Howe Sound. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 24p plus appendices.
- Thurber Consultants Ltd. 1983. Rogers Pass. Volume 2. Hydrology and debris flow potential. Report to CP Rail Special Projects, Calgary, AB.
- Thurber Consultants Ltd. 1985. Debris torrent assessment, Wahleach and Floods, Highway 1, Hope to Boston Bar Summit, Coquihalla Highway. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 27p plus appendices.
- Thurber Consultants Ltd. 1987. Debris torrent hazards along Highway 1, Sicamous to Revelstoke. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 20p plus appendices.

- VanDine, D.F. 1985. Debris flows and debris torrents in the Southern Canadian Cordillera. *Canadian Geotechnical Journal*, 22(1):44-68.
- VanDine, D.F. 1985. Debris flows and debris torrents in the Southern Canadian Cordillera: reply. *Canadian Geotechnical Journal*. 22(4):608-609.
- VanDine, D.F., Jordan, P. and Boyer, D. 1999. Perry Ridge, an example of a risk assessment for forestry planning. *In Proceedings, Confronting Uncertainty: Managing Change in Water Resources and the Environment*, Richmond, BC. Canadian Water Resources Association, BC Chapter, p255-262.
- Wilford, D.J and Schwab, J.W. 1982. Soil mass movements in the Rennell Sound area, Queen Charlotte Islands, British Columbia. *In Proceedings, Symposium of Canadian Hydrology*, Fredericton, NB, 21 p.
- Young, S.E. 1992. Analysis of slope failure and logging relationships in the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.

Section D General Papers/Review Papers

- Bovis, M.J., Dagg, B.R. and Kaye, D. 1985. Debris flows and debris torrents in the southern Canadian Cordillera: discussion. *Canadian Geotechnical Journal*, 22(4):608.
- Eisbacher, G.H. 1982. Mountain torrents and debris flows. *Episodes*, 4(1):12-17.
- Eisbacher, G.H. and Clague, J.J. 1984. Destructive mass movements in high mountains: hazard and management. Geological Survey of Canada, Paper 84-16, 230p.
- Fannin, R.J. and Rollerson, T.P. 1993. Debris flows: some physical characteristics and behaviour. *Canadian Geotechnical Journal*, 30(1):71-81.
- Fannin, R.J., Wise, M.P., Wilkinson, J.M.T., Thomson, B. and Hetherington, E.D. 1997. Debris flow hazard assessment in British Columbia. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p197-206.*
- Harris, S.A. and Gustafson, C.A. 1988. Retrogressive slumps, debris flows and river valley development in icy, unconsolidated sediments on hills and mountains. *Zeitschrift fur Geomorphologie*, 32(4):441-455.
- Hungr, O., Evans, S.G., Bovis, M.J and Hutchinson, J.N. In press. A review of the classification of landslides of the flow type. *Environmental and Engineering Geoscience*
- Hungr, O., Morgan, G.C. and Kellerhals, R. 1984. Quantitative analysis of debris torrent hazards for the design of remedial measures. *Canadian Geotechnical Journal*, 21:663-677.
- Jakob, M. 1996. Debris flows - curse of the mountains. *Geography Review*, 9(5):34-36.
- Jakob, M. and Skermer, N. [translators]. 1997. Debris flow. Translation from German of J. Stiny, *Die Muren, 1910. EBA Engineering Consultants Ltd, Vancouver, BC, 105p.*
- Lister, D.R. 1988. Litigation resulting from debris torrent activity along Howe Sound. *In Proceedings, Risk and Liability in Geotechnical Engineering, Vancouver Geotechnical Society, Vancouver, BC.*
- Miles, M.J. and Kellerhals, R. 1981. Some engineering aspects of debris torrents. *In Proceedings, 5th Canadian Hydrotechnical Conference, Fredericton NB, Canadian Society of Civil Engineers.*
- Russell, S.O.D. 1990. Debris torrents and professional responsibilities. *American Society of Civil Engineers, Journal of Professional Activities, Jan 1990.*
- Slaymaker, O. 1988. The distinctive attributes of debris torrents. *Hydrological Sciences Journal*, 33(6):567-573.
- VanDine Geological Engineering. 1986. Development of awareness, knowledge and mitigation of debris torrents in British Columbia. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 31p.
- VanDine, D.F. 1985. Debris flows and debris torrents in the Southern Canadian Cordillera. *Canadian Geotechnical Journal*, 22(1):44-68.
- VanDine, D.F. 1985. Debris flows and debris torrents in the Southern Canadian Cordillera: reply. *Canadian Geotechnical Journal*. 22(4):608-609.
- VanDine, D.F. 1992. Low magnitude - high frequency mass movements. *In Proceedings, Workshop on Geologic Hazards in British Columbia, Victoria, BC. British Columbia Geological Survey Branch Open File 1992-15, p99-107.*
- VanDine, D.F. and Lister, D.R.. 1983. Debris torrents - a new natural hazard?. *BC Professional Engineer, December, p9-11.*

Section E Initiation: Conditions, Frequencies

- Bovis, M.J. and Dagg, B.R. 1988. A model for debris accumulation and mobilization in steep mountain streams. *Journal of Hydrological Sciences*, 33(6):589-604.
- Bovis, M.J. and Dagg, B.R. 1992. Debris flow triggering by impulsive loading: mechanical modelling and case studies. *Canadian Geotechnical Journal*, 29(3):345-352.
- Bovis, M.J. and Jakob, M. 1999. The role of debris supply conditions in predicting debris flow activity. *Earth Surface Processes and Landforms*, 24(11):1039-1054.
- Bovis, M.J. and Millard, T.H. 1992. Precipitation thresholds for debris flow initiation in the southern Coast Mountains of British Columbia. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p309.*
- Brardinoni, F. In prep. The frequency distribution of small debris flows in the Capilano River basin. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Brayshaw, D.D. 1997. Factors affecting post-logging debris flow initiation in steep forested gullies of the southwestern Canadian Cordillera, Fraser Valley region. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Buchanan, P. and Savigny, K.W. 1990. Factors controlling debris avalanche initiation. *Canadian Geotechnical Journal*, 27:659-675.
- Buchanan, P., Savigny, K.W. and De Vries, J. 1990. A method for modelling water tables at debris avalanche headscarps. *Journal of Hydrology*, 113:61-88.
- Church, M. and Miles, M.J. 1987. Meteorological antecedents to debris flow in southwestern British Columbia: some case studies. *In Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation, Reno, NV. J.E. Costa and G.F. Wieczorek (editors). Reviews in Engineering Geology 7, Geological Society of America, Boulder, CO, p63-79.*
- Curry, G.E. and Mann, A.S. 1965. Estimating precipitation in a remote headwater area of western Alberta. *In Proceedings, 33rd Annual Meeting of the Western Snow Conference, Colorado Springs, CO, p58-66.*
- Dagg, B.R. 1987. Debris supply torrent-prone channels on the east side of Howe Sound, British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Davidson, S.C. 1998. Hydrologic controls of landsliding in Tsitika basin, Vancouver Island. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Evans, S.G. and Clague, J.J. 1997. The impact of climate change on catastrophic geomorphic processes in the mountains of British Columbia, Yukon and Alberta. *In Responding to Global Climate Change in British Columbia and Yukon. Volume 1 of the Canada Country Study: Climate Impacts and Adaptation. E. Taylor and B. Taylor (editors). British Columbia Ministry of Environment, Lands and Parks and Environment Canada, Vancouver, BC, p7:1-7:16.*
- Eyles, N. and Clague, J.J. 1987. Landsliding caused by Pleistocene glacial lake ponding - an example from central British Columbia. *Canadian Geotechnical Journal*, 24(4):656-663.
- Fannin R.J. and Jaakkola, J.J. 1999. Hydrological response of hillslope soils above a debris-slide headscarp. *Canadian Geotechnical Journal*, 36(6):1111-1122.
- Fannin, R.J., Jaakkola, J., Wilkinson, J.M.T. and Hetherington, E.D. In press. The hydrological response of soils to rainfall at Carnation Creek, British Columbia. *Water Resources Research.*
- Harris, S.A. and McDermid, G. 1998. Frequency of debris flows on the Sheep Mountain fan, Kluane Lake, Yukon Territory. *Zeitschrift fur Geomorphologie*, 42(2):159-175.

- Hogan, D.L. and J.W. Schwab. 1991. Meteorological conditions associated with hillslope failures on the Queen Charlotte Islands. British Columbia Ministry of Forest, Land Management Report 73, Victoria, BC.
- Jaakkola, J.J. 1998. Forest groundwater hydrology: implications for terrain stability in coastal British Columbia. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.
- Jaakkola, J.J. and Fannin, R.J. 1999. Analysis of hillslope piezometric records: implications for terrain stability. *In Proceedings, 13th Annual Vancouver Geotechnical Society Symposium*, Vancouver, BC, p671-680.
- Jackson, Jr., L.E. 1979. A catastrophic glacial outburst flood (jokulhlaup) mechanism for debris flow generation at the Spiral Tunnels, Kicking Horse River basin, British Columbia. *Canadian Geotechnical Journal*, 16(4):806-813.
- Jacob, N. 2000. Debris flow activity in a forest environment, Gaspésie, Québec: triggering, frequency and magnitude. Masters thesis, Université Laval, Department of Geography (Centres d'Études Nordiques), Laval QU, 96p.
- Jakob, M. 1996. Morphometric and geotechnical controls of debris flow frequency and magnitude in southwestern British Columbia. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Jakob, M. and Bovis, M.J. 1996. Morphometric and geotechnical controls of debris flow activity, southern Coast Mountains, British Columbia, Canada. *Zeitschrift fur Geomorphologie, N.F.*, 104:13-26.
- Jakob, M. and Podor, A. 1995. Frequency and magnitude of debris flows. *In Proceedings, 48th Canadian Geotechnical Conference*, Vancouver, BC. Canadian Geotechnical Society, p491-498.
- Millard, T. 1999. Debris flow initiation in coastal British Columbia gullies. British Columbia Ministry of Forests, Vancouver Forest Region, Technical Report, TR-002, 22p.
- Oden, M.E. 1994. Debris recharge rates in tormented gullies on the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- O'Loughlin, C.L. 1972. Investigation of the stability of the steepland forest soils in the Coast Mountains, southwest British Columbia. Ph.D. thesis, University of British Columbia, Department of Geography, Vancouver, BC, 147p.
- Rollerson, T.R., Thomson, B. and Millard, T.H. 1997. Identification of coastal British Columbia terrain susceptible to debris flows. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation*, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p484-495.
- Schwab, J.W. 1998. Debris avalanches-flows on British Columbia's north coast. *In Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions*. D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Wilkinson, J.M.T., 1996. Landslide initiation: a unified geostatistical and probabilistic modelling technique for terrain stability assessment. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.

Section F Transportation and Deposition/Debris Fans

- Boyer, D. 1999. Debris flow hazards on alluvial fans: Kootenay Region, southeast BC. *In* Proceedings, *Confronting Uncertainty: Managing Change in Water Resources and the Environment*, Richmond, BC. Canadian Water Resources Association, BC Chapter, p325-327.
- Desloges, J.R. and Gardner, J.S. 1984. Process and discharge estimation in ephemeral channels, Canadian Rocky Mountains. *Canadian Journal of Earth Sciences*, 21:1050-1060.
- Fannin, R.J., Rollerson, T.R., Hogan, D.L. and Daust, D. 1992. Characteristics of a large debris flow channel. *In* Proceedings, *Geotechnique and Natural Hazards, a Symposium*, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p311-318.
- Gardner, J.S. 1981. Ephemeral and episodic transport of debris on mountain slopes. Progress Report on Research Conducted Under Permit from Parks Canada, Western Region Parks Canada, Calgary, AB, 22p.
- Gardner, J.S. 1986. Sediment movement in ephemeral streams on mountain slopes, Canadian Rocky Mountains. *In* Proceedings, *Hillslope Processes, Binghamton Symposia in Geomorphology*. A.D. Abraham, editor. International Series 16, Allen & Unwin Inc, Winchester, p97-113.
- Jones, N.K. 1987. Debris transport and deposition at Boundary Glacier, Banff National Park, Alberta. PhD thesis, University of Waterloo, Waterloo, ON.
- Kostaschuk, R.A., MacDonald, G.M. and Jackson, Jr., L.E. 1987. Rocky Mountain alluvial fans. *The Canadian Geographer*, 31(4):366-368.
- Kostaschuk, R.A., MacDonald, G.M. and Putman, P. 1986. Depositional process and alluvial fan-drainage basin morphometric relationships near Banff, Alberta. *Earth Surface Processes and Landforms*, 11:471-484.
- Thomson, B. 1986. Potential introduced rapid mass movement debris rating map : Smokey Creek-Falls Creek. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheets 82F.043 and 82F.053).*
- Thomson, B. 1989. Pemberton Creek: potential clearcut landslide and stream impact rating. Ministry of Environment Lands and Parks, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheet 92J.036).
- Wilford, D.J. and Sidle, R.C. 1999. Forestry on fans: linking geomorphic processes to site prescriptions. 1999. In Abstracts, Fall Meeting of the American Geophysical Union, San Francisco, CA.
- Winder, C.G. 1965. Alluvial cone construction by alpine mudflow in a humid temperate region. *Canadian Journal of Earth Sciences*, 2:270-277.

Section G Rheology

- Evans, S.G., Hungr, O. and Clague, J.J. In press. The 1984 rock avalanche from the western flank of Mt. Cayley, British Columbia: description and dynamic analysis of a hyper-mobile landslide. *Engineering Geology*.
- Fannin, R.J. and Rollerson, T.P. 1993. Debris flows: some physical characteristics and behaviour. *Canadian Geotechnical Journal*, 30(1):71-81.
- Galay, V.J., Rood, K. and Hungr, O. 1992. Dynamics of hazards within watersheds. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p299-307.*
- Hungr, O. 1985. Transport mechanisms in debris flows of the Canadian Cordillera. *Geological Society of America, Boulder, CO, Abstracts with Program, 17:362.*
- Hungr, O. 1988. Notes on dynamic analysis of flowslides. *In Proceedings, 5th International Symposium on Landslides, Lausanne, Switzerland, p679-683.*
- Hungr, O. 1993. Mass-referenced flow model for dynamic analysis of flow slides and avalanches. Invited paper *in Proceedings, "Pierre Beghin" International Workshop on Rapid Gravitational Movements, Grenoble University press, p145-151.*
- Hungr, O. 1997. Analysis of the motion of a debris avalanche event. *Chikyu ("Earth") magazine, Japan, special issue focused on debris flow hazards. H.Fukuoka (editor), 19:661-665 (translated into Japanese).*
- Hungr, O. In press. Analysis of debris flow surges using the theory of uniformly progressive flow. *Earth Surface Processes and Landforms.*
- Hungr, O. and Evans, S.G. 1997. A dynamic model for landslides with changing mass. *In Proceedings, Symposium on Engineering Geology and the Environment, International Association of Engineering Geology, Athens, Greece, p719-724.*
- Hungr, O. and McClung, D.M. 1987. An equation for calculating snow avalanche run-up against barriers. *In Avalanche Formation, Motion and Effects, IAHS Publication 162, p605-612.*
- Hungr, O. and Morgenstern, N.R. 1984. Experiments in high velocity open channel flow of granular materials. *Géotechnique, 34: 405-413*
- Hungr, O. and Morgenstern, N.R. 1984. Experiments in high velocity open channel flow of granular materials: reply. *Géotechnique, 35: 383-385.*
- Hungr, O. and Morgenstern, N.R., 1984. High velocity ring shear tests on sand. *Géotechnique, 34:415-421.*
- Hungr, O., Morgan, G.C. and Kellerhals, R. 1984. Quantitative analysis of debris torrent hazards for the design of remedial measures. *Canadian Geotechnical Journal, 21:663-677.*
- Hungr, O., Dawson, R., Kent, A., Campbell, D. and Morgenstern, N.R., In press. Rapid flow slides of coal mine waste in British Columbia, Canada. *In Catastrophic Landslides, Reviews in Engineering Geology, Geological Society of America, Boulder, CO.*
- Hungr, O., Evans, S.G., Bovis, M.J and Hutchinson, J.N. In press. A review of the classification of landslides of the flow type. *Environmental and Engineering Geoscience*
- Jordan, P. 1991. Dynamic behavior and material properties of debris flows in the southern Coast Mountains, British Columbia. *In Program with Abstracts, Geological Association of Canada Annual Meeting, Vancouver BC, pA66.*
- Jordan, R.P. 1995. Debris flows in the southern Coast Mountains, British Columbia: dynamic behaviour and physical properties. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Locat, J. 1992. Viscosity, yield strength, and mudflow mobility for sensitive clays and other fine sediments. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC.*

Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p389-396.

Locat, J. 1997. Normalized rheological behaviour of fine muds and their flow properties in a pseudoplastic regime. *In* Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p260-269.

Lu, Z.Y. 1993. Landslides and geotechnical properties of volcanic tuff on Mount Cayley, British Columbia. PhD thesis, University of Alberta, Department of Civil Engineering, Edmonton, AB, 263p.

Lu, Z.Y. and Cruden, D.M. 1998. Velocity-dependent local phenomena around an extremely rapid landslide. *In* Proceedings, 8th Congress of the International Association of Engineering Geology, Vancouver, BC, p1431-1436.

Miles, M.J. and Kellerhals, R. 1981. Some engineering aspects of debris torrents. *In* Proceedings, 5th Canadian Hydrotechnical Conference, Fredericton NB, Canadian Society of Civil Engineers.

Section H Sedimentology

- Beaudoin, A.B. and King, R.H. 1994. Holocene palaeoenvironmental record preserved in a paraglacial alluvial fan, Sunwapta Pass, Jasper National Park, Alberta, Canada.. *Catena*, 22(3):227-248.
- Benvenuti, M. and Martini, P. 1997. Sedimentological facies analysis on alluvial, highly concentrated-flow deposits. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p496-505.*
- Brevik, E.C. and Reid, J.R. 1993. Evidence for catastrophic debris flow in southern Manitoba. *In Proceedings, North Dakota Academy of Science, 47:46.*
- Brooks, G.R. 1992. Aspects of post-glacial sediment supply and its control upon the morphology of the Squamish River, southwestern British Columbia. PhD thesis, Simon Fraser University, Department of Geography, Burnaby, BC, 448 p.
- Church, M. and Ryder, J.M. 1989. Sedimentology and clast fabric of subaerial debris flow facies in a glacially-influenced alluvial-fan: discussion. *Sedimentary Geology, 65(1):195-196.*
- Cruden, D.M. and Lu, Z.Y. 1989. The geomorphic impact of the catastrophic October 1984 flood, on the platform of the Spanish River, southwest British Columbia. *Canadian Journal of Earth Sciences, 26:336.*
- Desloges, J.R. 1982. Sedimentology and paleohydrology of alpine multiple-process channels in southwestern Alberta. Masters thesis, University of Wisconsin, Department of Geography, Madison, WI, 216p.
- Eyles, N. and Kocsis, S. 1988. Sedimentology and clast fabric of subaerial debris flow fan facies in a glacially-influenced alluvial fan. *Sedimentology, 59:15-28.*
- Eyles, N., Eyles, C.H. and McCabe, A.M. 1988. Late Pleistocene subaerial debris-flow facies of the Bow Valley, near Banff, Canadian Rocky Mountains. *Sedimentology, 35:465-480.*
- Friele, P.A., Ekes, C. and Hickin, E.J. 1999. Evolution of Cheekeye fan, Squamish, British Columbia: Holocene sedimentation and implications for hazard assessment. *Canadian Journal of Earth Sciences, 36:2023-2031.*
- Hogan, D.L. 1986. Channel morphology of unlogged, logged, and debris torrented streams in the Queen Charlotte Islands. British Columbia Ministry of Forests and Lands, Land Management Report 49, Victoria, BC, 94p.
- Hogan, D.L., Bird, S.A. and Rice, S. 1998. Stream channel morphology and recovery processes. *In Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions. D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.*
- McPherson, H.J. and Hirst, F. 1972. Sediment changes on two alluvial fans in the Canadian Rocky Mountains. *In Mountain Geomorphology: Processes in the Canadian Cordillera. O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd, Vancouver, BC, p161-176.*
- Menzies, J. and Kamil Z. In prep. Microstructures within a modern debris flow deposit derived from a Quaternary glacial diamicton - a comparative micromorphological study. Brock University, Departments of Geography and Earth Sciences, St. Catherines, ON.
- Millard, T.H. 1993. Sediment in forested and logged gullies, coastal British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Oden, M.E. 1994. Debris recharge rates in torrented gullies on the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.

- Owens, I.F. 1972. Morphological characteristics of alpine mudflows in the Nigel Pass area. *In* Mountain Geomorphology: Processes in the Canadian Cordillera. O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd., Vancouver, BC, p93-100.
- Ryder, J.M. 1971. Some aspects of the morphology of paraglacial alluvial fans in south central British Columbia. *Canadian Journal of Earth Sciences*, 8:1252-1264.
- Ryder, J.M. 1971. The stratigraphy and morphology of para-glacial alluvial fans in south-central British Columbia. *Canadian Journal of Earth Science*, 8:279-298.

Section I Runout

- Ayotte, D. and Hungr, O. In press. Calibration of a runout prediction model for debris flows and avalanches. *In Proceedings, 2nd International Conference on Debris Flow Hazard Mitigation, Taipei, Taiwan.*
- Ayotte, D., Evans, N. and Hungr, O. 1999. Runout analysis of debris flows and avalanches in Hong Kong. *In Proceedings, 13th Vancouver Geotechnical Society Symposium, Vancouver, BC, p39-46.*
- Fannin, R.J. and Wise, M.P. 1995. Method for calculation of debris flow travel distance. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p643-650.*
- Golder Associates Ltd. 1995. Runout characteristics of debris from dump failures in mountainous terrain. Stage 2: analysis, modelling and prediction. Report to the British Columbia Mine Waste Rock Pile Research Committee and CANMET, 55p.
- Hungr, O. 1990. A mass change model for the estimation of debris flow runout: discussion. *Journal of Geology, 99:633-634.*
- Hungr, O. 1992. Runout prediction for flow-slides and avalanches: analytical methods. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p139-144.*
- Hungr, O. 1995. A model for the runout analysis of rapid flow slides, debris flows and avalanches. *Canadian Geotechnical Journal, 32(4):610-623.*
- Wise, M.P. 1997. Probabilistic modelling of debris flow travel distance using empirical volumetric relationships. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.

Section J Study Methodology

- British Columbia Ministry of Forests. 1995. Gully assessment procedure guidebook. Forest Practices Code of British Columbia, Victoria, BC.
- Buchanan, P., Savigny, K.W. and De Vries, J. 1990. A method for modelling water tables at debris avalanche headscarps. *Journal of Hydrology*, 113:61-88.
- Currie, M.V., Skermer, N., Jakob, M. and West-Sells, B. 1999. Debris flow hazards in North Vancouver District: how do we manage the risk? *In Proceedings, Confronting Uncertainty: Managing Change in Water Resources and the Environment*, Richmond, BC. Canadian Water Resources Association, BC Chapter, p12-14.
- Curry, G.E. and Mann, A.S. 1965. Estimating precipitation in a remote headwater area of western Alberta. *In Proceedings, 33rd Annual Meeting of the Western Snow Conference*, Colorado Springs, CO, p58-66.
- Desloges, J.R. and Gardner, J.S. 1984. Process and discharge estimation in ephemeral channels, Canadian Rocky Mountains. *Canadian Journal of Earth Sciences*, 21:1050-1060.
- Fannin, R.J., Wise, M.P., Wilkinson, J.M.T., Thomson, B. and Hetherington, E.D. 1997. Debris flow hazard assessment in British Columbia. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation*, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p197-206.
- Hawley, P.M. 1989. Identification, evaluation and mitigation of debris flow hazards in British Columbia. *In Proceedings, Conference XX, International Erosion Control Association*, Vancouver, BC, p471.
- Howes, D.E. 1987. A terrain evaluation method for predicting terrain susceptible to post-logging landslide activity. British Columbia Ministry of Environment, Technical Report 28, Victoria, BC, 38p.
- Hungr, O. and Jackson, Jr. L.E. 1992. A debris flow basin and event data base format with an example data set from southwestern British Columbia. Geological Survey of Canada, Open File Report 2522, 12p.
- Hungr, O. and McClung, D.M. 1987. An equation for calculating snow avalanche run-up against barriers. *In Avalanche Formation, Motion and Effects*, IAHS Publication 162, p605-612.
- Hungr, O., Sobkowicz, J.C. and Morgan, G.C. 1993. How to economize on natural hazards. *Geotechnical News*, 11:54-57.
- Hungr, O., Yau, H.W., Tse, C.M., Cheng, L.F. and Hardingham, A.D. 1998. Natural slope hazard and risk assessment framework. *In Proceedings, International Conference on Urban Ground Engineering*, Hong Kong. Institute of Civil Engineers.
- Jackson, Jr., L.E., Kostaschuk, R.A. and MacDonald, G.M. 1987. Identification of debris flow hazard on alluvial fans in the Canadian Rocky Mountains. *In Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation*, Reno, NV. J.E. Costa and G.F. Wieczorek (editors). *Reviews in Engineering Geology* 7, Geological Society of America, Boulder, CO, p115-124.
- Saczuk, E.A.R. 1996. Mapping geomorphic hazard sites using GIS between Bow Pass and Seebe in southwestern Alberta. Honours thesis, University of Manitoba, Winnipeg, MB, p56.
- Saczuk, E.A.R. 1998. GIS-based modelling of debris flows in Banff National Park, Alberta. Masters thesis, University of Manitoba, Winnipeg, MB, 101p.
- Saczuk, E.A.R. and Campbell, M. In prep. Tool for the estimation of volume of debris in debris flow channels.
- Saczuk, E.A.R. and Gardner, J.S. 1998. GIS-based mapping and modelling of debris flows in Banff National Park. *Canadian Journal of Remote Sensing*, 24(1):53-59.

- Sauchyn, M.A. 1983. Evaluation of botanical methods for dating debris flow deposits and estimating debris flow hazard in the Canadian Rocky Mountains. Masters thesis, University of Waterloo, Waterloo, ON, 147p.
- Sauchyn, M.A., Gardner, J.S. and Suffling, R. 1983. Evaluation of botanical methods of dating debris flows and debris flow hazard in the Canadian Rocky Mountains. *Physical Geography*, 2:182-201.
- Sobkowicz, J.C., Hungr, O. and Morgan, G.C. 1995. Probabilistic mapping of a debris flow hazard area. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p519-529.*
- Wilkinson, J.M.T. and Fannin, R.J. 1997. A probabilistic technique for terrain stability assessment of open slopes in coastal BC. *In Proceedings, 11th Annual Vancouver Geotechnical Society Symposium, Vancouver, BC, p17-30.*

Section K Mitigation

- Anderson, B.C., Haigh, T.R. and Smith, C.D. 1992. Geogrid reinforced soil and lock-block debris deflector for transmission towers. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p331-338.*
- Askin, R.W. 1995. Mountain logging in coastal British Columbia: environmental mitigation using geotechnical principles. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p745-754.*
- Currie, M.V., Skermer, N., Jakob, M. and West-Sells, B. 1999. Debris flow hazards in North Vancouver District: how do we manage the risk? *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC, p12-14.*
- Currie, M.V., Skermer, N.A., and West-Sells, R.J. 1996. Debris flow hazard mitigation at Upper Mackay Creek, North Vancouver. *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC.*
- Eisbacher, G.H. and Clague, J.J. 1984. Destructive mass movements in high mountains: hazard and management. Geological Survey of Canada, Paper 84-16, 230p.
- Hawley, P.M. 1989. Identification, evaluation and mitigation of debris flow hazards in British Columbia. *In Proceedings, Conference XX, International Erosion Control Association, Vancouver, BC, p471.*
- Hungr, O. 1993. Flood and debris flow mitigation for the proposed Whistler Creek redevelopment. *In Proceedings, Whistler and Water, Building a City in the Mountains. A.G. Chantler (editor). Canadian Water Resources Association, BC Chapter, p97-103.*
- Hungr, O. and McClung, D.M. 1987. An equation for calculating snow avalanche run-up against barriers. *In Avalanche Formation, Motion and Effects, IAHS Publication 162, p605-612.*
- Hungr, O. and Rawlings, G. 1995. Terrain hazards assessment for planning purposes: Cheekeye Fan, BC. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p509-517.*
- Hungr, O., Morgan, C.C., VanDine, D.F. and Lister, D.R. 1987. Debris flow defenses in British Columbia. *In Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation, Reno, NV. J.E. Costa and G.F. Wiczorek (editors). Reviews in Engineering Geology 7, Geological Society of America, Boulder, CO, p63-79.*
- Hungr, O., Morgan, G.C. and Kellerhals, R. 1984. Quantitative analysis of debris torrent hazards for the design of remedial measures. *Canadian Geotechnical Journal, 21:663-677.*
- Klohn Leonoff Ltd. 1992. Debris torrents. *In Functional Design Study of the Sea to Sky Highway. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC.*
- Martin, D.C. 1989. Remedial measures for debris flows in British Columbia. *Bulletin Association of Engineering Geology, 25:265-276.*
- Martin, D.C., Piteau, D.R., Pearce, R.A. and Hawley, P.M. 1984. Remedial measures for debris flows at the Agassiz Mountain Institution, British Columbia. *Canadian Geotechnical Journal, 21(3):505-517.*
- Miles, M.J., Kellerhals R. and A.H. Rice. 1992. Performance of buried fiber optic telecommunications cable subjected to debris torrent events Coquihalla Corridor, British Columbia. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p339-346.*

- Morgan, G.C., Rawlings, G.E. and Sobkowicz, J.C. 1992. Evaluating total risk to communities from large debris flows. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p225-236.*
- Murray, D.N., Currie, M.V., Skermer, N.A. and Henry, W.K. 1998. Design and construction of the Upper Mackay Creek debris basin in North Vancouver District. *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC.*
- Nasmith, H.W. and Mercer, A.G. 1979. Design of dykes to protect against debris flows at Port Alice, British Columbia. *Canadian Geotechnical Journal, 16(4):748-757.*
- Price, J. 1986. Debris torrent control facilities, Vancouver, BC, Canada. *IABSE Periodica 3/1986, IABSE Structures C-38/86, p60-61.*
- Radomske, E. 1999. Hazard mitigation after the fact: the June 1990 debris flow accident on Philpott Road, Okanagan Valley. *In Program and Abstracts, 42nd Annual Meeting of the Western Division of the Canadian Association of Geographers, Okanagan University College, Kelowna, BC.*
- Skermer, N.A. 1985. The control of debris flows. *In Proceedings, 81st Annual Meeting of the Geological Society of America, Cordillera Section, Vancouver, BC, p408-425.*
- [[Strilaeff, P.W. 1984. Debris torrent alert system for Alberta Creek at Lions Bay, BC *Professional Engineer, v35(2):14-16.*]]
- Thurber Consultants Ltd. 1984. Debris torrents, a review of mitigative measures. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 32p plus appendices.
- Thurber Consultants Ltd./Ker Priestman & Associates Ltd. 1986. Harvey and Magnesia Creek debris-torrent structures. *Canadian Consulting Engineer, September / October 1986, p51-52.*
- Tripp, D. 1986. Using large organic debris to restore fish habitat in debris-torrented streams. *British Columbia Ministry of Forests and Lands, Land Management Report 47, 26p.*
- Tse, C.M., Chu, T., Wu, R., Hungr, O. and Li, F.H. 1999. A risk-based approach to landslide hazard mitigation design. *In Proceedings, Hong Kong Institution of Engineers, Geotechnical Division Annual Seminar, Hong Kong, p35-42.*
- VanDine Geological Engineering. 1992. Design of mitigative works for Boat Launch Creek, Kennedy Lake, BC. Report to British Columbia Ministry of Forests, Port Alberni District, Port Alberni, BC, 16p.
- VanDine, D.F. 1996. Debris flow control structures for forest engineering. *British Columbia Ministry of Forests Working Paper 22/1996, Victoria, BC, 75p.*
- VanDine, D.F., Hungr, O., Lister, D.R., and Chatwin, S.C. 1997. Channelized debris flow mitigation structures in British Columbia. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p605-615.*
- Wise, M.P. 1996. Debris flow control structure Escalante River WRP. *In Proceedings, Coastal Forest Site Rehabilitation Workshop, BC Forestry Continuing Studies Network, Nanaimo, BC.*

Section L Theses

- Brardinoni, F. In prep. The frequency distribution of small debris flows in the Capilano River basin. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Brayshaw, D.D. 1997. Factors affecting post-logging debris flow initiation in steep forested gullies of the southwestern Canadian Cordillera, Fraser Valley region. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Brooks, G.R. 1992. Aspects of post-glacial sediment supply and its control upon the morphology of the Squamish River, southwestern British Columbia. PhD thesis, Simon Fraser University, Department of Geography, Burnaby, BC, 448 p.
- Carr, K. 1989. Debris flow hazard in the Cathedral Mountain area, Kicking Horse Pass, British Columbia: causes, effects and response to the risk. Undergraduate paper, Wilfred Laurier University, Department of Earth Sciences, Waterloo, ON, 32p.
- Dagg, B.R. 1987. Debris supply torrent-prone channels on the east side of Howe Sound, British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Davidson, S.C. 1998. Hydrologic controls of landsliding in Tsitika basin, Vancouver Island. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Desloges, J.R. 1982. Sedimentology and paleohydrology of alpine multiple-process channels in southwestern Alberta. Masters thesis, University of Wisconsin, Department of Geography, Madison, WI, 216p.
- Gustafson, C.A. 1985. Debris flows along the Slims River valley, Kluane National Park, Yukon Territory. Masters thesis, University of Calgary, Calgary, AB.
- Jaakkola, J.J. 1998. Forest groundwater hydrology: implications for terrain stability in coastal British Columbia. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.
- Jacob, N. 2000. Debris flow activity in a forest environment, Gaspésie, Québec: triggering, frequency and magnitude. Masters thesis, Université Laval, Department of Geography (Centres d'Études Nordiques), Laval QU, 96p.
- Jakob, M. 1996. Morphometric and geotechnical controls of debris flow frequency and magnitude in southwestern British Columbia. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Jones, N.K. 1987. Debris transport and deposition at Boundary Glacier, Banff National Park, Alberta. PhD thesis, University of Waterloo, Waterloo, ON.
- Jordan, R.P. 1995. Debris flows in the southern Coast Mountains, British Columbia: dynamic behaviour and physical properties. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Lu, Z.Y. 1993. Landslides and geotechnical properties of volcanic tuff on Mount Cayley, British Columbia. PhD thesis, University of Alberta, Department of Civil Engineering, Edmonton, AB, 263p.
- Millard, T.H. 1993. Sediment in forested and logged gullies, coastal British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Oden, M.E. 1994. Debris recharge rates in torrented gullies on the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- O'Loughlin, C.L. 1972. Investigation of the stability of the steepland forest soils in the Coast Mountains, southwest British Columbia. Ph.D. thesis, University of British Columbia, Department of Geography, Vancouver, BC, 147p.

- Owens, I.F. 1973. Alpine mudflows in the Nigel Pass area, Canadian Rocky Mountains. PhD thesis, University of Toronto, Department of Geography, Toronto, ON, 218p.
- Podor, A.P. 1992. Recent debris flow frequency and magnitude at West Wilson Creek, Banff National Park, Alberta. Masters thesis, University of Waterloo, Waterloo, ON, 221p.
- Saczuk, E.A.R. 1996. Mapping geomorphic hazard sites using GIS between Bow Pass and Seebe in southwestern Alberta. Honours thesis, University of Manitoba, Winnipeg, MB, p56.
- Saczuk, E.A.R. 1998. GIS-based modelling of debris flows in Banff National Park, Alberta. Masters thesis, University of Manitoba, Winnipeg, MB, 101p.
- Sauchyn, M.A. 1983. Evaluation of botanical methods for dating debris flow deposits and estimating debris flow hazard in the Canadian Rocky Mountains. Masters thesis, University of Waterloo, Waterloo, ON, 147p.
- Sauchyn, M.A.. 1984. Open rock basins and debris fans in the Kananaskis area, southern Canadian Rocky Mountains. Unpublished Ph.D. dissertation. University of Waterloo, Waterloo, ON.
- Sterling, S.M. 1997. Influence of bedrock type on the magnitude, frequency and spatial distribution of debris torrents on northern Vancouver Island, BC. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC, 117 p.
- Wilkinson, J.M.T., 1996. Landslide initiation: a unified geostatistical and probabilistic modelling technique for terrain stability assessment. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.
- Wise, M.P. 1997. Probabilistic modelling of debris flow travel distance using empirical volumetric relationships. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.
- Young, S.E. 1992. Analysis of slope failure and logging relationships in the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.

Section M Field Guides/Field Trips

- Church, M. 1984. Debris torrents and natural hazards of steep channels: east shore of Howe Sound. Field Trip 7 Guidebook. Canadian Association of Geographers Annual Meeting, Nanaimo, British Columbia. University of British Columbia, Department of Geography, 83p.
- Church, M. 1985. Debris torrents and natural hazards of steep mountain channels: east shore of Howe Sound. Field-Trip 4 Guidebook. *In* Jackson, Jr. L.E., Church, M., Clague, J.J. and Eisbacher, G.M. Slope hazards in the southern Coast Mountains of British Columbia. Geological Society of America, Cordilleran Section Annual Meeting, Vancouver, British Columbia.
- Eisbacher, G.H. 1983. Slope stability and mountain torrents, Fraser lowland and southern Coast Mountains, British Columbia. Field Trip Guidebook 15. Geological Association of Canada Meeting, Victoria, BC.
- Hungr, O. and Skermer, N. 1992. Debris torrents and rockslides, Howe Sound to Whistler corridor. Field Trip Guidebook, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers.
- Jackson Jr, L.E. 1996. Slope hazards investigation trip to Kicking Horse Pass, British Columbia. Informal field trip guidebook, Vancouver, BC.
- Lister, D.R. and Morgan, G.C. 1989. Debris torrents along Howe Sound, British Columbia. Field Trip Excursion Guidebook. Conference XX, International Erosion Control Association, Vancouver, BC.
- [[Lister, D.R. and Morgan, G.C. 1989. Debris torrents along Howe Sound, British Columbia. Field Trip Excursion Guidebook. Conference XX, International Erosion Control Association, Vancouver, BC.]]
- Slaymaker, O. 1990. Natural hazards in mountain terrain: Howe Sound, British Columbia. Field Tour, Canadian Association of Geographers, Western Division Annual Meeting, University of British Columbia, Vancouver, BC, 53p.
- Slaymaker, O., Hungr, O., Desloges, J., Lister, D.R., Miles, M.J. and VanDine, D.F. 1987. Debris torrent and debris flood hazards, Lower Fraser, Nicolum and Coquihalla valleys, BC. Excursion B2. International Association of Hydrological Sciences Symposium on Forest Hydrology and Watershed Management, 70 p.
- Thurber Consultants Ltd and Ker Priestman & Associates Ltd. No date. Site visit to debris torrent facilities at Charles Creek, Harvey Creek, Magnesia Creek, Alberta Creek, Lions Bay, BC. Field Guide.

Section N Forestry-related Studies/Reports

- Askin, R.W. 1995. Mountain logging in coastal British Columbia: environmental mitigation using geotechnical principles. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p745-754.*
- Bartle, H.T., Rollerson, T.P. and Thomson, B. 1997. Report on the May 31, 1997 Gowan Creek debris flow and fatality. Report to British Columbia Ministry of Forests, Squamish Forest District, 13 p.*
- Baumann Engineering. 1997. Level II slide assessments, Hesquiat Lake, near Boat Basin, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Baumann Engineering. 1997. Level II slide assessments, Kanim Lake, near Hotsprings Cove, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Brayshaw, D.D. 1997. Factors affecting post-logging debris flow initiation in steep forested gullies of the southwestern Canadian Cordillera, Fraser Valley region. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- British Columbia Ministry of Forests. 1995. Gully assessment procedure guidebook. Forest Practices Code of British Columbia, Victoria, BC.
- Carson, B.R., Thomson, B., Hogan, D. and Bates, D. 1998. Slope failures, water quality and stream channel morphology: a case study. *In Proceedings, 8th Congress International Association of Engineering Geology and the Environment, Vancouver, BC. D. Moore and O. Hungr (editors), p2017-2024.*
- Cass, D.E., Kenning, B.F.I. and Rawlings, G. 1992 The Philpott Road debris failures – Kelowna, BC, 1990. the impacts of geology, hydrology and logging activities. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p319-330.*
- Chatwin, S.C. and Smith, R.B. 1992. Reducing soil erosion associated with forestry operations through integrated research: an example from coastal British Columbia, Canada. *In Proceedings, Erosion, Debris Flows and Environment in Mountain Regions, IASG Publication, 209:377-385.*
- Howes, D.E. 1987. A terrain evaluation method for predicting terrain susceptible to post-logging landslide activity. British Columbia Ministry of Environment, Technical Report 28, Victoria, BC, 38p.
- Jaakkola, J.J. 1998. Forest groundwater hydrology: implications for terrain stability in coastal British Columbia. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.
- Jacob, N. 2000. Debris flow activity in a forest environment, Gaspésie, Québec: triggering, frequency and magnitude. Masters thesis, Université Laval, Department of Geography (Centres d'Études Nordiques), Laval QU, 96p.
- Jakob, M. 1999. The impacts of logging on landslide activity at Clayoquot Sound, Vancouver Island, British Columbia. *Catena 38(4):279-300.*
- Jakob, M. 2000. Trees, water and soil - landslides in British Columbia. *Geography Review 13(3):12-15.*
- Krag, R.K., Sauder, E. A. and Welburn, G.V. 1986. A forest engineering analysis of landslides in logged areas on the Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Land Management Report 43, Victoria BC, 138p.

- Millard, T., Wise, M.P., Rollerson, T.R., Chatwin, S. and Hogan, D. 1998. Gully system hazards, risks, and forestry operations in coastal British Columbia. *In* Proceedings, 8th Congress of the International Association of Engineering Geology, Vancouver, BC.
- Millard, T.H. 1993. Sediment in forested and logged gullies, coastal British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- O'Loughlin, C.L. 1972. Investigation of the stability of the steepland forest soils in the Coast Mountains, southwest British Columbia. Ph.D. thesis, University of British Columbia, Department of Geography, Vancouver, BC, 147p.
- Rood, K.M. 1990. Site characteristics and landsliding in forested and clearcut terrain, Queen Charlotte Islands, BC. British Columbia Ministry of Forests, Land Management Report 64, Victoria, BC, 46p.
- Sauder, E.A., Krag, R.K. and Wellburn, G.V. 1987. Logging and mass wasting in the Pacific Northwest with application to the Queen Charlotte Islands, BC: a literature review. British Columbia Ministry of Forests, Land Management Report 53, Victoria, BC, 26p.
- Schwab, J.W. 1983. Mass wasting: October-November 1978 storm, Rennell Sound, Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Research Note 91, Victoria BC.
- Slaymaker, O. In press. Assessment of the geomorphic impacts of forestry in British Columbia. *Ambio*.
- VanDine Geological Engineering. 1990. Geological engineering assessment of the Ottawa Hill (Slocan Valley) debris torrents of May 1990. Report to British Columbia Ministry of Forests, Arrow Forest District, 16p plus appendices.*
- VanDine Geological Engineering. 1991. Kennedy Lake 1991 slope failures. Report to Fletcher Challenge Canada and MacMillan Bloedel Limited, Nanaimo, BC, 22p plus appendices.*
- VanDine, D.F. 1996. Debris flow control structures for forest engineering. British Columbia Ministry of Forests Working Paper 22/1996, Victoria, BC, 75p.
- Wilford, D.J. and Sidle, R.C. 1999. Forestry on fans: linking geomorphic processes to site prescriptions. 1999. In Abstracts, Fall Meeting of the American Geophysical Union, San Francisco, CA.
- Young, S.E. 1992. Analysis of slope failure and logging relationships in the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.

Section O Debris flows mentioned in regional/general landslide studies/reports

- Abrams, A. 1979. Present geological hazards and soil sensitivity to earthquake movement for the Lower Mainland Official Regional Plan review. British Columbia Ministry of Environment, Victoria, BC, 18p.
- Alley, N.F. and Thomson, B. 1978. Aspects of environmental geology, parts of Graham Island, Queen Charlotte Islands. British Columbia Ministry of Environment, Resource Analysis Branch, Victoria, BC.
- Batterson, M., Liverman, D.G.E., Ryan, J. and Taylor, D. 1999. The assessment of geological hazards and disasters in Newfoundland: an update. Newfoundland Department of Mines and Energy, Geological Survey, Report 99-1:95-123.
- Baumann Engineering. 1997. Level II slide assessments, Hesquiat Lake, near Boat Basin, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Baumann Engineering. 1997. Level II slide assessments, Kanim Lake, near Hotsprings Cove, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Bovis, M.J. 1993. Hillslope geomorphology and geotechnique. *Progress in Physical Geography*, 17(2):173-189.
- British Columbia Environment and Land Use Secretariat. 1980. Howe Sound, an overview study. Victoria, BC, 131p.
- British Columbia Ministry of Transportation and Highways. 1996. Natural hazards recognition manual. Geotechnical Engineering and Materials Branch, Victoria, BC.
- Brooks, G.R. 1992. Aspects of post-glacial sediment supply and its control upon the morphology of the Squamish River, southwestern British Columbia. PhD thesis, Simon Fraser University, Department of Geography, Burnaby, BC, 448 p.
- Buchanan, R. and Abrams, A. 1979. Preliminary geological hazards – Howe Sound. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Carson, B.R., Thomson, B., Hogan, D. and Bates, D. 1998. Slope failures, water quality and stream channel morphology: a case study. *In Proceedings, 8th Congress International Association of Engineering Geology and the Environment*, Vancouver, BC. D. Moore and O. Hungr (editors), p2017-2024.
- Chatwin, S.C., Howes, D.E., Schwab, J.W. and Swanston, D.N. 1994. A guide for management of landslide-prone terrain in the Pacific Northwest. 2nd edition. British Columbia Ministry of Forests, Land Management Handbook 18, 220p.
- Clague, J.J. 1978 Terrain hazards in the Skeena and Kitimat River basins, British Columbia. Geological Survey of Canada, Paper 78-1A, p183-188.
- Clague, J.J. 1981. Landslides at the south end of Kluane Lake, Yukon Territory. *Canadian Journal of Earth Sciences*, 18(5):959-971.
- Clague, J.J. 1987. Catastrophic outburst floods. *Geoscience Canada*, 16(2):18-21.
- Cruden, D.M. 1985. Rock slope movements in the Canadian Cordillera. *Canadian Geotechnical Journal*, 22:528-540.
- Eisbacher, G.H. 1979. First order regionalization of landslide characteristics in the Canadian Cordillera. *Geoscience Canada*, 6(2):69-79.
- Eisbacher, G.H. 1982. Slope stability and land use in mountain valleys. *Geoscience Canada*, 9:14-27.

- Eisbacher, G.H. and Clague, J.J. 1981. Urban landslides in the vicinity of Vancouver, British Columbia, with special reference to the December 1979 rainstorm. *Canadian Geotechnical Journal*, 18:205-216.
- Evans, S.G. 1982. Landslides and surficial deposits in urban areas of British Columbia: a review. *Canadian Geotechnical Journal*, 19:269-288.
- Evans, S.G. and Clague, J.J. 1989. Rain-induced landslides in the Canadian Cordillera, July 1988. *Geoscience Canada*, 16:193-200.
- Evans, S.G. and Clague, J.J. 1997. The impact of climate change on catastrophic geomorphic processes in the mountains of British Columbia, Yukon and Alberta. *In Responding to Global Climate Change in British Columbia and Yukon. Volume 1 of the Canada Country Study: Climate Impacts and Adaptation.* E. Taylor and B. Taylor (editors). British Columbia Ministry of Environment, Lands and Parks and Environment Canada, Vancouver, BC, p7:1-7:16.
- Evans, S.G. and Savigny, K.W. 1994. Landslides in the Vancouver - Fraser Valley - Whistler region. *In Geology and Geological Hazards of the Vancouver Region, Southwestern British Columbia.* J.W.H. Monger (editor). Geological Survey of Canada, Bulletin 481, p251-286.
- Galay, V.J., Rood, K. and Hungr, O. 1992. Dynamics of hazards within watersheds. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC.* Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p299-307.
- Gardner, J.S. 1982. Alpine mass-wasting in contemporary time, some examples from the Canadian Rocky Mountains. *In Proceedings, Space and Time in Geomorphology, Binghampton Symposium.* C.E. Thorn (editor). International Series 12, George Allen and Unwin, p171-192.
- Gardner, J.S. 1982. Alpine mass-wasting in contemporary time, some examples from the Canadian Rocky Mountains. *In Proceedings, Space and Time in Geomorphology, Binghampton Symposium.* C.E. Thorn (editor). International Series 12, George Allen and Unwin, p171-192.
- Gimbarzevsky, P. 1988. Mass wasting on the Queen Charlotte Islands - a regional inventory. British Columbia Ministry of Forests, Land Management Report 29, 96p.
- Grainger, W. 1999. Investigation of 22 landslides in Upper Chase Creek, BC. *In Proceedings, 13th Vancouver Geotechnical Society Symposium, Vancouver, BC,* p97-106.
- Harris, S.A. and Gustafson, C.A. 1988. Retrogressive slumps, debris flows and river valley development in icy, unconsolidated sediments on hills and mountains. *Zeitschrift fur Geomorphologie*, 32(4):441-455.
- Howes, D.E. 1981. Terrain inventory and geological hazards: northern Vancouver Island. British Columbia Ministry of Environment, Assessment and Planning Division, APD Bulletin 5, Victoria, BC.
- Hungr, O. and Smith, D. 1985. Landslides and development in the lower mainland, British Columbia. *BC Professional Engineer*, 36:11-14.
- Hungr, O., Yau, H.W., Tse, C.M., Cheng, L.F. and Hardingham, A.D. 1998. Natural slope hazard and risk assessment framework. *In Proceedings, International Conference on Urban Ground Engineering, Hong Kong.* Institute of Civil Engineers.
- Jakob, M. 1999. The impacts of logging on landslide activity at Clayoquot Sound, Vancouver Island, British Columbia. *Catena* 38(4):279-300.
- Jakob, M. 2000. Trees, water and soil - landslides in British Columbia. *Geography Review* 13(3):12-15.
- Jordan, P. 1987. Impacts of mass movement events on rivers in the southern Coast Mountains, British Columbia: summary report. Report to Environment Canada, Inland Waters Directorate, Sediment Survey IWD-HQ-WRB-SS-87-3.

- Jordan, P. and Slaymaker, O. 1991. Holocene sediment production in Lillooet River basin, British Columbia: a sediment budget approach. *Geographie physique et Quaternaire*, 45(1):45-57.
- Klohn Leonoff Limited. 1994. Flood hazard management plan. Report to the Regional District of Squamish, BC.
- Krag, R.K., Sauder, E. A. and Welburn, G.V. 1986. A forest engineering analysis of landslides in logged areas on the Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Land Management Report 43, Victoria BC, 138p.
- Locat, J. and Cruden, D.M. 1977. Major landslides in the eastern slopes of the southern Canadian Rockies. *In Proceedings, 15th Annual Idaho Symposium on Engineering Geology and Soils*, Boise, ID, p179-197.
- O'Loughlin, C.L. 1972. A preliminary study of landslides in the Coast Mountains of southwestern British Columbia. *In Mountain Geomorphology: Processes in the Canadian Cordillera*. O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd., Vancouver, BC, p101-112.
- Rood, K.M. 1984. An aerial photograph inventory of frequency and yield of mass wasting on the Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Land Management Report 34, Victoria BC.
- Rood, K.M. 1990. Site characteristics and landsliding in forested and clearcut terrain, Queen Charlotte Islands, BC. British Columbia Ministry of Forests, Land Management Report 64, Victoria, BC, 46p.
- Ryder, J.M. 1998. Geomorphological processes in alpine areas of Canada: the effects of climate change and their impacts on human activities. Geological Survey of Canada, Bulletin 524, 44p.
- Sauder, E.A., Krag, R.K. and Wellburn, G.V. 1987. Logging and mass wasting in the Pacific Northwest with application to the Queen Charlotte Islands, BC: a literature review. British Columbia Ministry of Forests, Land Management Report 53, Victoria, BC, 26p.
- Schwab, J.W. 1998. Landslides on the Queen Charlotte Islands: processes, rates and climatic events. *In Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions*. D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Septer, D. and Schwab, J.W. 1995. Rainstorm and flood damage: northwest British Columbia 1891-1991. British Columbia Ministry of Forests, Land Management Handbook 31, Victoria BC.
- Skermer, N. 1993. Landslides in the mountains. *In Proceedings, Canadian Water Resources Association, BC Chapter*, Vancouver, BC, p85-90.
- Slaymaker, O. 1988. Slope erosion and mass movement in relation to weathering in geochemical cycles. *In Physical and Chemical Weathering in Geochemical Cycles*. A Lerman and M. Meybeck (editors). Kluwer Academic, Rotterdam, p83-111.
- Slaymaker, O. 1990. Climate change and erosion processes in mountain regions of western Canada. *Mountain Research and Development*, 10:171-182.
- Slaymaker, O. 1993. The sediment budget of the Lillooet River basin. *Physical Geography*, 14:304-320.
- Slaymaker, O. 1999. Natural hazards in British Columbia: an interdisciplinary and inter-institutional challenge. *International Journal of Earth Sciences*, 88:317-324.

- Slaymaker, O. and McPherson, H.J. (editors). 1972. Mountain Geomorphology: Processes in the Canadian Cordillera. BC Geographical Series 14, Tantalus Research Ltd., Vancouver, BC, 274p.
- Slaymaker, O. and McPherson, H.J., 1977. An overview of geomorphic processes in the Canadian Cordillera. *Zeitschrift fur Geomorphologie*, 21:169-186.
- Slaymaker, O. In press. Assessment of the geomorphic impacts of forestry in British Columbia. *Ambio*.
- Thomson, B. 1983. Terrain features and geological processes maps and legends for the Goat-Milk River Project Area (NTS 93H/7). British Columbia Ministry of Environment, Victoria, BC.*
- Thomson, B. 1987. Chapman Creek landslide inventory. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend.*
- Thomson, B. 1989. Pemberton Creek: potential clearcut landslide and stream impact rating. Ministry of Environment Lands and Parks, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheet 92J.036).
- Tse, C.M., Chu, T., Wu, R., Hungr, O. and Li, F.H. 1999. A risk-based approach to landslide hazard mitigation design. *In Proceedings, Hong Kong Institution of Engineers, Geotechnical Division Annual Seminar, Hong Kong*, p35-42.
- VanDine, D.F., Jordan, P. and Boyer, D. 1999. Perry Ridge, an example of a risk assessment for forestry planning. *In Proceedings, Confronting Uncertainty: Managing Change in Water Resources and the Environment, Richmond, BC. Canadian Water Resources Association, BC Chapter*, p255-262.
- Ward, B.C., Jackson, L.E. and Savigny, K.W. 1992. Evolution of Surprise Rapids landslide, Yukon Territory. Geological Survey of Canada, Paper 90-18, 25p.
- Wilford, D.J and Schwab, J.W. 1982. Soil mass movements in the Rennell Sound area, Queen Charlotte Islands, British Columbia. *In Proceedings, Symposium of Canadian Hydrology, Fredericton, NB*, 21 p.

Section P Consulting reports and/or government internal reports (these citations may not necessarily be available to the public)

- Bartle, H.T., Rollerson, T.P. and Thomson, B. 1997. Report on the May 31, 1997 Gowan Creek debris flow and fatality. Report to British Columbia Ministry of Forests, Squamish Forest District, 13 p.*
- Baumann Engineering. 1997. Level II slide assessments, Hesquiat Lake, near Boat Basin, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Baumann Engineering. 1997. Level II slide assessments, Kanim Lake, near Hotsprings Cove, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Buchanan, R. and Abrams, A. 1979. Preliminary geological hazards – Howe Sound. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Church, M. and Russell, S.O.D. 1983. Recent history and condition of Alberta Creek at Lions Bay, British Columbia: implications for the safety of settlement at Lions Bay. University of British Columbia, Vancouver, BC, internal report.
- EBA Engineering Consultants Ltd. 1996. Debris flow initiation potential, gully assessment procedures, and meteorological conditions associated with debris flows in the Kalum Forest District, northwestern British Columbia. Report to Ministry of Forests, Prince Rupert Region, 32p.*
- EBA Engineering Consultants Ltd. 1998. Hillside industrial park debris flow, debris flood and landslide hazard assessment, Port Mellon, BC. Report to Sunshine Coast Regional District.*
- EBA Engineering Consultants Ltd. 1998. History of debris floods on Susap Creek fan, lower Similkameen Valley. Report to Canada Department of Indian and Northern Affairs, Vancouver, BC.*
- EBA Engineering Consultants Ltd. 1999. Clementine Creek debris flow investigation. Report to Burrard Yacht Club, Vancouver, BC.*
- EBA Engineering Consultants Ltd. 2000. Deroche Creek debris flow and debris flood study. Report to Fraser Valley Regional District.*
- Golder Associates Ltd. 1962. Landslide on Canadian Pacific Railway at Twin Butte, British Columbia. Report to Canadian Wheat Board.*
- Golder Associates Ltd. 1990. Debris torrent hazard assessment kilometre 1020, Floods, BC. Report to Trans-Mountain Pipeline Company Ltd, Vancouver, BC.*
- Golder Associates Ltd. 1990. Philpott Road potential for slides and debris flows, Kelowna. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Hardy, R.M., Morgenstern, N.R. and Patton, F.D. 1978. Report of the Garibaldi "the Barrier" Advisory Panel (3 parts). British Columbia Department of Highways, Victoria, BC, 321p.*
- Jones, W.C. 1959. Cheekeye River mudflows. British Columbia Department of Mines, Victoria, BC, memorandum, 9p.*
- Kerr Wood Liedal Ltd./EBA Engineering Consultants Ltd. 1999. Overview report on debris flow hazards. Report to District of North Vancouver, BC.*
- Klohn Leonoff Limited. 1994. Flood hazard management plan. Report to the Regional District of Squamish, BC.*
- Klohn Leonoff Ltd. 1992. Debris torrents. *In* Functional Design Study of the Sea to Sky Highway. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC.*

- Klohn-Crippen Consultants Ltd. 1998. Terrain stability inventory - alluvial and debris torrent fans, Kootenay Region. Report to British Columbia Ministry of Environment Lands and Parks, Kootenay Region.*
- Lister, D.R. 1983. Chilliwack to Hope debris torrents, near Wahleach. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lister, D.R. 1988. Slocan Lake (north end) potential debris flow. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lister, D.R. 1991. Debris torrent 33km north of Sayward. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Piteau Associates Ltd. 1993. Mount Goslin debris torrent hazard study, Tete Jaune Cache. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch.*
- Readshaw, E.E. 1968. Camp Creek slide. Internal report. British Columbia Ministry of Highways, Victoria, BC.*
- Rollerson, T.P., Millard, T.P. and Thomson, B. 1997. Bridal Creek area preliminary terrain hazard reconnaissance 1997. Report to BC Ministry of Forests, Chilliwack Forest District, 13p.*
- Terratech Consulting Ltd. 1999. Detailed terrain stability mapping (TSIL C) Hummingbird Creek and Mara Creek watersheds. Map and Report to Riverside Forest Products Ltd.*
- Thomson, B. 1983. Terrain features and geological processes maps and legends for the Goat-Milk River Project Area (NTS 93H/7). British Columbia Ministry of Environment, Victoria, BC.*
- Thomson, B. 1986. Potential introduced rapid mass movement debris rating map : Smokey Creek-Falls Creek. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheets 82F.043 and 82F.053).*
- Thomson, B. 1987. Chapman Creek landslide inventory. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend.*
- Thomson, B. 1989. Pemberton Creek: potential clearcut landslide and stream impact rating. Ministry of Environment Lands and Parks, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheet 92J.036).
- Thurber Consultants Ltd. 1977. Fitzsimmons Creek, Whistler, British Columbia, geotechnical review of landslides and debris flows. Report to British Columbia Ministry of Environment, Land Management Branch, Victoria, BC, 8p.*
- Thurber Consultants Ltd. 1984. Schlufield Creek debris torrent, December 14, 1984. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Thurber Consultants. Ltd. 1976. Port Alice Rumble Beach debris flow. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- VanDine Geological Engineering Limited. 1998. Assessment of debris flow potential of Newman Creek, Howe Sound. Report to British Columbia Ministry of Transportation and Highways, South Coast Region, Burnaby, BC, 11p.*
- VanDine Geological Engineering Limited. 1999. Reconnaissance of M (Yahoo) Creek. Report to BC Rail, North Vancouver, BC, 6p.*

- VanDine Geological Engineering. 1986. Development of awareness, knowledge and mitigation of debris torrents in British Columbia. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 31p.*
- VanDine Geological Engineering. 1990. Geological engineering assessment of the Ottawa Hill (Slocan Valley) debris torrents of May 1990. Report to British Columbia Ministry of Forests, Arrow Forest District, 16p plus appendices.*
- VanDine Geological Engineering. 1991. Kennedy Lake 1991 slope failures. Report to Fletcher Challenge Canada and MacMillan Bloedel Limited, Nanaimo, BC, 22p plus appendices.*
- VanDine Geological Engineering. 1992. Design of mitigative works for Boat Launch Creek, Kennedy Lake, BC. Report to British Columbia Ministry of Forests, Port Alberni District, Port Alberni, BC, 16p.*

Section Q Geographical region**Alberta**

- Beaudoin, A.B. and King, R.H. 1994. Holocene palaeoenvironmental record preserved in a paraglacial alluvial fan, Sunwapta Pass, Jasper National Park, Alberta, Canada.. *Catena*, 22(3):227-248.
- Couture, R. and Evans, S.G. 2000. Five-Mile Creek debris flow, Banff National Park, near Banff, Alberta, August 4th, 1999. Geological Survey of Canada, Open File 3876.
- Couture, R. and Evans, S.G. 2000. The East Gate landslide, Beaver Valley, Glacier National Park, Columbia Mountains, British Columbia. Geological Survey of Canada, Open File 3877.
- Curry, G.E. and Mann, A.S. 1965. Estimating precipitation in a remote headwater area of western Alberta. *In Proceedings, 33rd Annual Meeting of the Western Snow Conference, Colorado Springs, CO*, p58-66.
- Desloges, J.R. 1982. Sedimentology and paleohydrology of alpine multiple-process channels in southwestern Alberta. Masters thesis, University of Wisconsin, Department of Geography, Madison, WI, 216p.
- Desloges, J.R. and Gardner, J.S. 1984. Process and discharge estimation in ephemeral channels, Canadian Rocky Mountains. *Canadian Journal of Earth Sciences*, 21:1050-1060.
- Eyles, N., Eyles, C.H. and McCabe, A.M. 1988. Late Pleistocene subaerial debris-flow facies of the Bow Valley, near Banff, Canadian Rocky Mountains. *Sedimentology*, 35:465-480.
- Gardner, J.S. 1981. Ephemeral and episodic transport of debris on mountain slopes. Progress Report on Research Conducted Under Permit from Parks Canada, Western Region Parks Canada, Calgary, AB, 22p.
- Gardner, J.S. 1982. Alpine mass-wasting in contemporary time, some examples from the Canadian Rocky Mountains. *In Proceedings, Space and Time in Geomorphology, Binghamton Symposium*. C.E. Thorn (editor). International Series 12, George Allen and Unwin, p171-192.
- Gardner, J.S. 1986. Sediment movement in ephemeral streams on mountain slopes, Canadian Rocky Mountains. *In Proceedings, Hillslope Processes, Binghamton Symposia in Geomorphology*. A.D. Abraham (editor). International Series 16, Allen & Unwin Inc, Winchester, p97-113.
- Jackson, Jr., L.E. 1987. Debris flow hazard in the Canadian Rocky Mountains, Geological Survey of Canada, Paper 86-11, 10p.
- Jackson, Jr., L.E., Kostaschuk, R.A. and MacDonald, G.M. 1987. Identification of debris flow hazard on alluvial fans in the Canadian Rocky Mountains. *In Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation, Reno, NV*. J.E. Costa and G.F. Wieczorek (editors). Reviews in Engineering Geology 7, Geological Society of America, Boulder, CO, p115-124.
- Jones, N.K. 1987. Debris transport and deposition at Boundary Glacier, Banff National Park, Alberta. PhD thesis, University of Waterloo, Waterloo, ON.
- Kostaschuk, R.A., MacDonald, G.M. and Jackson, Jr., L.E. 1987. Rocky Mountain alluvial fans. *The Canadian Geographer*, 31(4):366-368.
- Kostaschuk, R.A., MacDonald, G.M. and Putman, P. 1986. Depositional process and alluvial fan-drainage basin morphometric relationships near Banff, Alberta. *Earth Surface Processes and Landforms*, 11:471-484.
- Locat, J. and Cruden, D.M. 1977. Major landslides in the eastern slopes of the southern Canadian Rockies. *In Proceedings, 15th Annual Idaho Symposium on Engineering Geology and Soils, Boise, ID*, p179-197.

- Podor, A.P. 1992. Recent debris flow frequency and magnitude at West Wilson Creek, Banff National Park, Alberta. Masters thesis, University of Waterloo, Waterloo, ON, 221p.
- Saczuk, E.A.R. 1996. Mapping geomorphic hazard sites using GIS between Bow Pass and Seebe in southwestern Alberta. Honours thesis, University of Manitoba, Winnipeg, MB, p56.
- Saczuk, E.A.R. 1998. GIS-based modelling of debris flows in Banff National Park, Alberta. Masters thesis, University of Manitoba, Winnipeg, MB, 101p.
- Saczuk, E.A.R. and Gardner, J.S. 1998. GIS-based mapping and modelling of debris flows in Banff National Park. *Canadian Journal of Remote Sensing*, 24(1):53-59.
- Sauchyn, M.A. 1983. Evaluation of botanical methods for dating debris flow deposits and estimating debris flow hazard in the Canadian Rocky Mountains. Masters thesis, University of Waterloo, Waterloo, ON, 147p.
- Sauchyn, M.A. 1984. Open rock basins and debris fans in the Kananaskis area, southern Canadian Rocky Mountains. Unpublished Ph.D. dissertation. University of Waterloo, Waterloo, ON.
- Sauchyn, M.A., Gardner, J.S. and Suffling, R. 1983. Evaluation of botanical methods of dating debris flows and debris flow hazard in the Canadian Rocky Mountains. *Physical Geography*, 2:182-201.
- VanDine, D.F. 1985. Debris flows and debris torrents in the Southern Canadian Cordillera. *Canadian Geotechnical Journal*, 22(1):44-68.
- Winder, C.G. 1965. Alluvial cone construction by alpine mudflow in a humid temperate region. *Canadian Journal of Earth Sciences*, 2:270-277.

British Columbia

Subdivided by BC Ministry of Transportation and Highways Regions

Region 1: South Coast (Lower Mainland, Southwest BC)

Region 2: Thompson-Okanagan (South Central BC)

Region 3: Kootenays (Southeast BC)

Region 4: Central/North East

Region 5: North West

Region 6: Vancouver Island

BC General: (General citations relating to British Columbia)

- Bovis, M.J., Dagg, B.R. and Kaye, D. 1985. Debris flows and debris torrents in the southern Canadian Cordillera: discussion. *Canadian Geotechnical Journal*, 22(4):608.
- British Columbia Ministry of Forests. 1995. Gully assessment procedure guidebook. Forest Practices Code of British Columbia, Victoria, BC.
- British Columbia Ministry of Transportation and Highways. 1996. Natural hazards recognition manual. Geotechnical Engineering and Materials Branch, Victoria, BC.
- Evans, S.G. 1982. Landslides and surficial deposits in urban areas of British Columbia: a review. *Canadian Geotechnical Journal*, 19:269-288.
- Eyles, N. 1987. Late Pleistocene debris-flow deposits in large glacial lakes in British Columbia and Alaska. *Sedimentary Geology*, 53(1-2):33-71.
- Hawley, P.M. 1989. Identification, evaluation and mitigation of debris flow hazards in British Columbia. *In Proceedings, Conference XX, International Erosion Control Association, Vancouver, BC, p471.*
- Hungr, O. 1985. Transport mechanisms in debris flows of the Canadian Cordillera. *Geological Society of America, Boulder, CO, Abstracts with Program*, 17:362.

- Hungr, O., Morgan, C.C., VanDine, D.F. and Lister, D.R. 1987. Debris flow defenses in British Columbia. *In Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation*, Reno, NV. J.E. Costa and G.F. Wiczorek (editors). *Reviews in Engineering Geology* 7, Geological Society of America, Boulder, CO, p63-79.
- Jakob, M. 2000. Trees, water and soil - landslides in British Columbia. *Geography Review* 13(3):12-15.
- Martin, D.C. 1989. Remedial measures for debris flows in British Columbia. *Bulletin Association of Engineering Geology*, 25:265-276.
- Millard, T.H, Wise, M.P., Rollerson, T.R., Chatwin, S. and Hogan, D. 1998. Gully system hazards, risks, and forestry operations in coastal British Columbia. *In Proceedings, 8th Congress International Association of Engineering Geology and the Environment*, Vancouver, BC. D. Moore and O. Hungr (editors)
- Owens, P. and Slaymaker, O. 1992. Late Holocene sediment yields in small and subalpine drainage basins, British Columbia. *In Erosion, Debris Flows and Environment in Mountain Regions*. D.E. Walling, T.R. Davies and B. Hasholt (editors). *International Association of Hydrological Sciences Publication* 209, p147-154.
- Slaymaker, O. 1999. Natural hazards in British Columbia: an interdisciplinary and inter-institutional challenge. *International Journal of Earth Sciences*, 88:317-324.
- Slaymaker, O. 1999. Regional controls on debris flows in British Columbia. *In Proceedings, 2nd National Taiwanese Debris Flow Conference*, Hualien, Taiwan.
- Slaymaker, O. In press. Assessment of the geomorphic impacts of forestry in British Columbia. *Ambio*.
- Tripp, D. 1986. Using large organic debris to restore fish habitat in debris-torrented streams. *British Columbia Ministry of Forests and Lands, Land Management Report* 47, 26p.
- VanDine Geological Engineering. 1986. Development of awareness, knowledge and mitigation of debris torrents in British Columbia. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 31p.*
- VanDine, D.F. 1985. Debris flows and debris torrents in the Southern Canadian Cordillera. *Canadian Geotechnical Journal*, 22(1):44-68.
- VanDine, D.F. 1992. Low magnitude - high frequency mass movements. *In Proceedings, Workshop on Geologic Hazards in British Columbia*, Victoria, BC. *British Columbia Geological Survey Branch Open File* 1992-15, p99-107.
- VanDine, D.F. 1996. Debris flow control structures for forest engineering. *British Columbia Ministry of Forests Working Paper* 22/1996, Victoria, BC, 75p.
- VanDine, D.F., Hungr, O., Lister, D.R., and Chatwin, S.C. 1997. Channelized debris flow mitigation structures in British Columbia. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation*, San Francisco, USA. C.-I. Chen (editor). *American Society of Civil Engineers*, New York, p605-615.

BC Region 1: South Coast (Lower Mainland, Southwest BC)

- Abrams, A. 1979. Present geological hazards and soil sensitivity to earthquake movement for the Lower Mainland Official Regional Plan review. *British Columbia Ministry of Environment*, Victoria, BC, 18p.
- Bartle, H.T., Rollerson, T.P. and Thomson, B. 1997. Report on the May 31, 1997 Gowan Creek debris flow and fatality. Report to British Columbia Ministry of Forests, Squamish Forest District, 13 p.*

- Bovis, M.J. and Jakob, M. In press. The July 30, 1998 debris flow and landslide dam at Capricorn Creek, Mount Meager Volcanic Complex, British Columbia. *Canadian Journal of Earth Sciences*.
- Bovis, M.J. and Millard, T.H. 1992. Precipitation thresholds for debris flow initiation in the southern Coast Mountains of British Columbia. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p309.*
- Brardinoni, F. In prep. The frequency distribution of small debris flows in the Capilano River basin. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Brayshaw, D.D. 1997. Factors affecting post-logging debris flow initiation in steep forested gullies of the southwestern Canadian Cordillera, Fraser Valley region. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- British Columbia Environment and Land Use Secretariat. 1980. Howe Sound, an overview study. Victoria, BC, 131p.
- Brooks, G.R. 1992. Aspects of post-glacial sediment supply and its control upon the morphology of the Squamish River, southwestern British Columbia. PhD thesis, Simon Fraser University, Department of Geography, Burnaby, BC, 448 p.
- Buchanan, R. and Abrams, A. 1979. Preliminary geological hazards – Howe Sound. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Carson, B.R., Thomson, B., Hogan, D. and Bates, D. 1998. Slope failures, water quality and stream channel morphology: a case study. *In Proceedings, 8th Congress International Association of Engineering Geology and the Environment, Vancouver, BC. D. Moore and O. Hungr (editors), p2017-2024.*
- Chatwin, S.C. and Smith, R.B. 1992. Reducing soil erosion associated with forestry operations through integrated research: an example from coastal British Columbia, Canada. *In Proceedings, Erosion, Debris Flows and Environment in Mountain Regions, IASG Publication, 209:377-385.*
- Church, M. 1984. Debris torrents and natural hazards of steep channels: east shore of Howe Sound. Field Trip 7 Guidebook. Canadian Association of Geographers Annual Meeting, Nanaimo, British Columbia. University of British Columbia, Department of Geography, 83p.
- Church, M. 1985. Debris torrents and natural hazards of steep mountain channels: east shore of Howe Sound. Field-Trip 4 Guidebook. *In Jackson, Jr. L.E., Church, M., Clague, J.J. and Eisbacher, G.M. Slope hazards in the southern Coast Mountains of British Columbia. Geological Society of America, Cordilleran Section Annual Meeting, Vancouver, BC.*
- Church, M. and Desloges, J.R. 1984. Debris torrents and natural hazards of steep mountain channels: east shore of Howe Sound: University of British Columbia, Department of Geography, Vancouver, BC, 83p.
- Church, M. and Miles, M.J. 1987. Meteorological antecedents to debris flow in southwestern British Columbia: some case studies. *In Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation, Reno, NV. J.E. Costa and G.F. Wieczorek (editors). Reviews in Engineering Geology 7, Geological Society of America, Boulder, CO, p63-79.*
- Church, M. and Russell, S.O.D. 1983. Recent history and condition of Alberta Creek at Lions Bay, British Columbia: implications for the safety of settlement at Lions Bay. University of British Columbia, Vancouver, BC. internal report.

- Cruden, D.M. and Lu, Z.Y. 1989. The geomorphic impact of the catastrophic October 1984 flood, on the platform of the Spanish River, southwest British Columbia. *Canadian Journal of Earth Sciences*, 26:336.
- Cruden, D.M. and Lu, Z.Y. 1992. The rockslide and debris flow from Mount Cayley, BC, in June 1984. *Canadian Geotechnical Journal*, 29(4):614-626.
- Currie, M.V., Skermer, N., Jakob, M. and West-Sells, B. 1999. Debris flow hazards in North Vancouver District: how do we manage the risk? *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC*, p12-14.
- Currie, M.V., Skermer, N.A., and West-Sells, R.J. 1996. Debris flow hazard mitigation at Upper Mackay Creek, North Vancouver. *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC*.
- Dagg, B.R. 1987. Debris supply torrent-prone channels on the east side of Howe Sound, British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- EBA Engineering Consultants Ltd. 1998. Hillside industrial park debris flow, debris flood and landslide hazard assessment, Port Mellon, BC. Report to Sunshine Coast Regional District.*
- EBA Engineering Consultants Ltd. 1999. Clementine Creek debris flow investigation. Report to Burrard Yacht Club, Vancouver, BC.*
- EBA Engineering Consultants Ltd. 2000. Deroche Creek debris flow and debris flood study. Report to Fraser Valley Regional District.*
- Eisbacher, G.H. 1982. Howe Sound debris flows. *Geoscience Canada*, 9(2):132.
- Eisbacher, G.H. 1983. Slope stability and mountain torrents, Fraser lowland and southern Coast Mountains, British Columbia. Field Trip Guidebook 15. Geological Association of Canada Meeting, Victoria, BC.
- Eisbacher, G.H. and Clague, J.J. 1981. Urban landslides in the vicinity of Vancouver, British Columbia, with special reference to the December 1979 rainstorm. *Canadian Geotechnical Journal*, 18:205-216.
- Evans, S.G. and Lister, D.R. 1984. The geomorphological effects of the July 1983 rainstorms in the southern Cordillera and their impact on transportation facilities. *Geological Survey of Canada, Paper 84-1B*, p223-235.
- Evans, S.G. and Savigny, K.W. 1994. Landslides in the Vancouver - Fraser Valley - Whistler region. *In Geology and Geological Hazards of the Vancouver Region, Southwestern British Columbia*. J.W.H. Monger (editor). Geological Survey of Canada, Bulletin 481, p251-286.
- Evans, S.G., Hungr, O. and Clague, J.J. In press. The 1984 rock avalanche from the western flank of Mt. Cayley, British Columbia: description and dynamic analysis of a hyper-mobile landslide. *Engineering Geology*.
- Fannin, R.J. and Wilkinson, J.M.T. 1995. An analysis of the Jaminson Creek landslide. *In Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC*. Canadian Geotechnical Society, p635-642.
- Friele, P.A., Ekes, C. and Hickin, E.J. 1999. Evolution of Cheekeye fan, Squamish, British Columbia: Holocene sedimentation and implications for hazard assessment. *Canadian Journal of Earth Sciences*, 36:2023-2031.
- Golder Associates Ltd. 1990. Debris torrent hazard assessment kilometre 1020, Floods, BC. Report to Trans-Mountain Pipeline Company Ltd, Vancouver, BC.*
- Hardy, R.M., Morgenstern, N.R. and Patton, F.D. 1978. Report of the Garibaldi "the Barrier" Advisory Panel (3 parts). British Columbia Department of Highways, Victoria, BC, 321p.*

- Howes, D.E. 1987. A terrain evaluation method for predicting terrain susceptible to post-logging landslide activity. British Columbia Ministry of Environment, Technical Report 28, Victoria, BC, 38p.
- Hungr, O. 1993. Flood and debris flow mitigation for the proposed Whistler Creek redevelopment. *In* Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC, p97-103.
- Hungr, O. and Jackson, Jr. L.E. 1992. A debris flow basin and event data base format with an example data set from southwestern British Columbia. Geological Survey of Canada, Open File Report 2522, 12p.
- Hungr, O. and Rawlings, G. 1995. Terrain hazards assessment for planning purposes: Cheekeye Fan, BC. *In* Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p509-517.
- Hungr, O. and Skermer, N. 1992. Debris torrents and rockslides, Howe Sound to Whistler corridor. Field Trip Guidebook, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers.
- Hungr, O. and Smith, D. 1985. Landslides and development in the lower mainland, British Columbia. *BC Professional Engineer*, Vancouver, BC, 36:11-14.
- Jaakkola, J.J. 1998. Forest groundwater hydrology: implications for terrain stability in coastal British Columbia. Masters thesis, University of British Columbia, Department of Civil Engineering, Vancouver, BC.
- Jakob, M. 1996. Morphometric and geotechnical controls of debris flow frequency and magnitude in southwestern British Columbia. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Jakob, M. and Bovis, M.J. 1996. Morphometric and geotechnical controls of debris flow activity, southern Coast Mountains, British Columbia, Canada. *Zeitschrift fur Geomorphologie*, N.F., 104:13-26.
- Jakob, M., Hungr, O. and Thomson, B. 1997. Two debris flows with anomalously high magnitude. *In* Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p382-394.
- Jones, W.C. 1959. Cheekeye River mudflows. British Columbia Department of Mines, Victoria, BC, memorandum, 9p.*
- Jordan, P. 1987. Impacts of mass movement events on rivers in the southern Coast Mountains, British Columbia: summary report. Report to Environment Canada, Inland Waters Directorate, Sediment Survey IWD-HQ-WRB-SS-87-3.
- Jordan, P. 1990. Large debris flows in the Meager Creek volcanic complex, British Columbia. *Eos*, 71:1145. (Paper presented at American Geophysical Union, Pacific Northwest regional meeting, Seattle.)
- Jordan, P. 1991. Dynamic behavior and material properties of debris flows in the southern Coast Mountains, British Columbia. *In* Program with Abstracts, Geological Association of Canada Annual Meeting, Vancouver BC, pA66.
- Jordan, P. and Slaymaker, O. 1991. Holocene sediment production in Lillooet River basin, British Columbia: a sediment budget approach. *Geographie physique et Quaternaire*, 45(1):45-57.
- Jordan, R.P. 1995. Debris flows in the southern Coast Mountains, British Columbia: dynamic behaviour and physical properties. PhD thesis, University of British Columbia, Department of Geography, Vancouver, BC.

- Kerr Wood Liedal Ltd./EBA Engineering Consultants Ltd. 1999. Overview report on debris flow hazards. Report to District of North Vancouver, BC.*
- Klohn Leonoff Limited. 1994. Flood hazard management plan. Report to the Regional District of Squamish, BC.*
- Klohn Leonoff Ltd. 1992. Debris torrents. *In* Functional Design Study of the Sea to Sky Highway. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC.*
- Lister, D.R. 1983. Chilliwack to Hope debris torrents, near Wahleach. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Lister, D.R. 1988. Litigation resulting from debris torrent activity along Howe Sound. *In* Proceedings, Risk and Liability in Geotechnical Engineering, Vancouver Geotechnical Society, Vancouver, BC.
- Lister, D.R. and Morgan, G.C. 1989. Debris torrents along Howe Sound, British Columbia. Field Trip Excursion Guidebook. Conference XX, International Erosion Control Association, Vancouver, BC.
- Lister, D.R., Morgan, G.C., VanDine, D.F. and Kerr, J.G.W. 1984. Debris torrents in Howe Sound, British Columbia. *In* Proceedings, 4th International Symposium on Landslides, Toronto ON, p649-654.
- Lu, Z.Y. 1992. Prehistoric debris avalanches from Mount Cayley volcano, British Columbia: discussion. *Canadian Journal of Earth Sciences*, 29:1342-1343.
- Lu, Z.Y. 1993. Landslides and geotechnical properties of volcanic tuff on Mount Cayley, British Columbia. PhD thesis, University of Alberta, Department of Civil Engineering, Edmonton, AB, 263p.
- Lu, Z.Y. and Cruden, D.M. 1996. Two debris flow modes on Mount Cayley, British Columbia. *Canadian Geotechnical Journal*, 32(1):123-139.
- Martin, D.C., Piteau, D.R., Pearce, R.A. and Hawley, P.M. 1984. Remedial measures for debris flows at the Agassiz Mountain Institution, British Columbia. *Canadian Geotechnical Journal*, 21(3):505-517.
- Miles, M.J., Kellerhals R. and A.H. Rice. 1992. Performance of buried fiber optic telecommunications cable subjected to debris torrent events Coquihalla Corridor, British Columbia. *In* Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p339-346.
- Millard, T.H. 1993. Sediment in forested and logged gullies, coastal British Columbia. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Millard, T.H. 1999. Debris flow initiation in coastal British Columbia gullies. British Columbia Ministry of Forests, Vancouver Forest Region, Nanaimo, BC, Technical Report, TR-002, 22p.
- Moore, D.P. and Mathews, W.H. 1978. The Rubble Creek landslide, southwestern British Columbia. *Canadian Journal of Earth Sciences*, 15:1039-1052.
- Murray, D.N., Currie, M.V., Skermer, N.A. and Henry, W.K. 1998. Design and construction of the Upper Mackay Creek debris basin in North Vancouver District. *In* Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC.
- O'Loughlin, C.L. 1972. A preliminary study of landslides in the Coast Mountains of southwestern British Columbia. *In* Mountain Geomorphology: Processes in the Canadian Cordillera. O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd., Vancouver, BC, p101-112.

- O'Loughlin, C.L. 1972. Investigation of the stability of the steepland forest soils in the Coast Mountains, southwest British Columbia. Ph.D. thesis, University of British Columbia, Department of Geography, Vancouver, BC, 147p.
- Patton, F.D. 1976. The Devastation Glacier slide, Pemberton, B.C. Abstract *In* Symposium on Geomorphology of the Canadian Cordillera and its Bearing on the Mineral Deposits. Geological Association of Canada, Cordilleran Section, p26.
- Price, J. 1986. Debris torrent control facilities, Vancouver, BC, Canada. IABSE Periodica 3/1986, IABSE Structures C-38/86, p60-61.
- Rollerson, T.P., Millard, T.P. and Thomson, B. 1997. Bridal Creek area preliminary terrain hazard reconnaissance 1997. Report to BC Ministry of Forests, Chilliwack Forest District, 13p.*
- Rollerson, T.R., Thomson, B. and Millard, T.H. 1997. Identification of coastal British Columbia terrain susceptible to debris flows. *In* Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA. C.-I. Chen (editor). American Society of Civil Engineers, New York, p484-495.
- Skermer, N. and Russell, D. 1988. 28th of October (a day of coincidence for floods on Howe Sound). BC Professional Engineer, Vancouver, BC, May 1988, p21-23.
- Skermer, N.A. 1984. M Creek debris flow disaster. *In* Proceedings, Canadian Geotechnical Conference, Canadian Case Histories of Landslides, Toronto, ON, p187-194.
- Slaymaker, O. 1990. Debris torrent hazard in eastern Fraser and Coquihalla valleys. *Western Geography*. 1(1):34-48.
- Slaymaker, O. 1990. Natural hazards in mountain terrain: Howe Sound, British Columbia. Field Tour, Canadian Association of Geographers, Western Division Annual Meeting, University of British Columbia, Vancouver, BC, 53p.
- Slaymaker, O. 1993. The sediment budget of the Lillooet River basin. *Physical Geography*, 14:304-320.
- Slaymaker, O., Hungr, O., Desloges, J., Lister, D.R., Miles, M.J. and VanDine, D.F. 1987. Debris torrent and debris flood hazards, Lower Fraser, Nicolum and Coquihalla valleys, BC. Excursion B2. International Association of Hydrological Sciences Symposium on Forest Hydrology and Watershed Management, 70 p.
- Smith, H.R. and Patton, F.D. 1984. Comparison of the Devastation Glacier Slide with other high velocity debris flows. *In* Proceedings, 4th International Symposium on Landslides, Toronto, ON, Abstracts, p96.
- Sobkowicz, J.C., Hungr, O. and Morgan, G.C. 1995. Probabilistic mapping of a debris flow hazard area. *In* Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p519-529.
- Thomson, B. 1986. Potential introduced rapid mass movement debris rating map : Smokey Creek-Falls Creek. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheets 82F.043 and 82F.053).*
- Thomson, B. 1987. Chapman Creek landslide inventory. British Columbia Ministry of Environment, Victoria, BC, 1:20,000 scale map with expanded legend.*
- Thomson, B. 1989. Pemberton Creek: potential clearcut landslide and stream impact rating. Ministry of Environment Lands and Parks, Victoria, BC, 1:20,000 scale map with expanded legend (BC Grid Sheet 92J.036).*
- Thurber Consultants Ltd. 1977. Fitzsimmons Creek, Whistler, British Columbia, geotechnical review of landslides and debris flows. Report to British Columbia Ministry of Environment, Land Management Branch, Victoria, BC, 8p.*

- Thurber Consultants Ltd. 1983. Debris torrents and flooding hazards, Highway 99, Howe Sound. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 24p plus appendices.*
- Thurber Consultants Ltd. 1984. Schlufield Creek debris torrent, December 14, 1984. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Thurber Consultants Ltd. 1985. Debris torrent assessment, Wahleach and Floods, Highway 1, Hope to Boston Bar Summit, Coquihalla Highway. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 27p plus appendices.*
- Thurber Consultants Ltd./Ker Priestman & Associates Ltd. 1986. Harvey and Magnesia Creek debris-torrent structures. Canadian Consulting Engineer, September / October 1986, p51-52.
- Thurber Consultants Ltd./Ker Priestman & Associates Ltd. No date. Site visit to debris torrent facilities at Charles Creek, Harvey Creek, Magnesia Creek, Alberta Creek, Lions Bay, BC. Field Guide.
- Thurber Engineering Ltd and Golder Associates Ltd. 1992. Cheekeye River terrain hazard study. Report to British Columbia Ministry of Environment, Lands and Parks, Victoria, BC.*
- VanDine Geological Engineering Limited. 1998. Assessment of debris flow potential of Newman Creek, Howe Sound. Report to British Columbia Ministry of Transportation and Highways, South Coast Region, Burnaby, BC, 11p.*
- VanDine Geological Engineering Limited. 1999. Reconnaissance of M (Yahoo) Creek. Report to BC Rail, North Vancouver, BC, 6p.*
- Ward, P.R.B., Skermer, N.A. and LaCas, B.D. 1991. The 50-year flood on Fitzsimmons Creek, Whistler, British Columbia. BC Professional Engineer, Vancouver, BC, December 1991, p5-6.
- Wilkinson, J.M.T. and Fannin, R.J. 1997. A probabilistic technique for terrain stability assessment of open slopes in coastal BC. *In Proceedings, 11th Annual Vancouver Geotechnical Society Symposium, Vancouver, BC, p17-30.*
- Woods, P.J. 1984 A debris flow landslide at Port Moody. *In Proceedings, 37th Canadian Geotechnical Conference, Toronto, ON, p217-222.*

BC Region 2: Thompson-Okanagan (South Central BC)

- Cass, D.E., Kenning, B.F.I. and Rawlings, G. 1992 The Philpott Road debris failures – Kelowna, BC, 1990. the impacts of geology, hydrology and logging activities. *In Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p319-330.*
- Dumoulin, J. 1965. Her Majesty the Queen vs. Canadian Pacific Railway Company, Twin Butte mudslide judgement. Exchequer Court of Canada, Victoria, BC, 29p.
- EBA Engineering Consultants Ltd. 1998. History of debris floods on Susap Creek fan, lower Similkameen Valley. Report to Canada Department of Indian and Northern Affairs, Vancouver, BC.*
- Golder Associates Ltd. 1962. Landslide on Canadian Pacific Railway at Twin Butte, British Columbia. Report to Canadian Wheat Board.*
- Golder Associates Ltd. 1990. Philpott Road potential for slides and debris flows, Kelowna. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- Grainger, W. 1999. Investigation of 22 landslides in Upper Chase Creek, BC. *In Proceedings, 13th Vancouver Geotechnical Society Symposium, Vancouver, BC, p97-106.*
- Jakob, M., Hungr, O., Anderson, D., Fuller, T. and Ayotte, D. In press. The July 7, 1997 debris flow at Hummingbird Creek. *Canadian Geotechnical Journal.*

- Jakob, M., Martin, S., Skermer, N., Campbell, C., Anderson, D. and Fuller, T. 1998. A record breaking debris flow at Hummingbird Creek, Mara Lake, BC. *In Proceedings 8th Congress International Association of Engineering Geology and the Environment, Vancouver, BC.* D. Moore and O. Hungr (editors), p2091-2098.
- Radomske, E. 1999. Hazard mitigation after the fact: the June 1990 debris flow accident on Philpott Road, Okanagan Valley. *In Program and Abstracts, 42nd Annual Meeting of the Western Division of the Canadian Association of Geographers, Okanagan University College, Kelowna, BC.*
- Readshaw, E.E. 1968. Camp Creek slide. Internal report. British Columbia Ministry of Highways, Victoria, BC.*
- Ryder, J.M. 1971. Some aspects of the morphology of paraglacial alluvial fans in south central British Columbia. *Canadian Journal of Earth Sciences*, 8:1252-1264.
- Ryder, J.M. 1971. The stratigraphy and morphology of para-glacial alluvial fans in south-central British Columbia. *Canadian Journal of Earth Science*, 8:279-298.
- Terratech Consulting Ltd. 1999. Detailed terrain stability mapping (TSIL C) Hummingbird Creek and Mara Creek watersheds. Map and Report to Riverside Forest Products Ltd.*

BC Region 3: Kootenays (Southeast BC)

- Boyer, D. 1999. Debris flow hazards on alluvial fans: Kootenay Region, southeast BC. *In Proceedings, Canadian Water Resources Association, BC Chapter, Vancouver, BC*, p325-327.
- Carr, K. 1989. Debris flow hazard in the Cathedral Mountain area, Kicking Horse Pass, British Columbia: causes, effects and response to the risk. Undergraduate paper, Wilfred Laurier University, Department of Earth Sciences, Waterloo, ON, 32p.
- Evans, S.G. and Lister, D.R. 1984. The geomorphological effects of the July 1983 rainstorms in the southern Cordillera and their impact on transportation facilities. *Geological Survey of Canada, Paper 84-1B*, p223-235.
- Gardner, J.S. 1982. Alpine mass-wasting in contemporary time, some examples from the Canadian Rocky Mountains. *In Proceedings, Space and Time in Geomorphology, Binghamton Symposium.* C.E. Thorn (editor). International Series 12, George Allen and Unwin, p171-192.
- Gardner, J.S. 1986. Sediment movement in ephemeral streams on mountain slopes, Canadian Rocky Mountains. *In Proceedings, Hillslope Processes, Binghamton Symposia in Geomorphology.* A.D. Abraham (editor). International Series 16, Allen & Unwin Inc, Winchester, p97-113.
- Hungr, O., Dawson, R., Kent, A., Campbell, D. and Morgenstern, N.R., In press. Rapid flow slides of coal mine waste in British Columbia, Canada. *In Catastrophic Landslides, Reviews in Engineering Geology, Geological Society of America, Boulder, CO.*
- Jackson Jr, L.E. 1996. Slope hazards investigation trip to Kicking Horse Pass, British Columbia. Informal field trip guidebook, Vancouver, BC.
- Jackson, Jr., L.E. 1979. A catastrophic glacial outburst flood (jokulhlaup) mechanism for debris flow generation at the Spiral Tunnels, Kicking Horse River basin, British Columbia. *Canadian Geotechnical Journal*, 16(4):806-813.
- Jackson, Jr., L.E. 1979. Mystery flood solved: CPR records revealed the 1978 catastrophe was not unique. *Geos*, 8(3):2-4.
- Jackson, Jr., L.E. 1980. New evidence in the origin of the September 6, 1978 jokulhlaup from the Cathedral Glacier. *Geological Survey of Canada, Paper 80-1B*, p292-294.
- Jackson, Jr., L.E. 1987. Debris flow hazard in the Canadian Rocky Mountains, *Geological Survey of Canada, Paper 86-11*, 10p.

- Jackson, Jr., L.E., Hungr, O., Gardner, J.S. and MacKay, C. 1989. Cathedral mountain debris flows, Canada. *Bulletin International Association of Engineering Geology*, 40:35-54.
- Jackson, Jr., L.E., Kostaschuk, R.A. and MacDonald, G.M. 1987. Identification of debris flow hazard on alluvial fans in the Canadian Rocky Mountains. *In Proceedings, Debris Flows/Avalanches: Process, Recognition and Mitigation*, Reno, NV. J.E. Costa and G.F. Wieczorek (editors). *Reviews in Engineering Geology* 7, Geological Society of America, Boulder, CO, p115-124.
- Klohn-Crippen Consultants Ltd. 1998. Terrain stability inventory - alluvial and debris torrent fans, Kootenay Region. Report to British Columbia Ministry of Environment Lands and Parks, Kootenay Region.*
- Kostaschuk, R.A., MacDonald, G.M. and Jackson, Jr., L.E. 1987. Rocky Mountain alluvial fans. *The Canadian Geographer*, 31(4):366-368.
- Lister, D.R. 1988. Slocan Lake (north end) potential debris flow. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- McPherson, H.J. and Hirst, F. 1972. Sediment changes on two alluvial fans in the Canadian Rocky Mountains. *In Mountain Geomorphology: Processes in the Canadian Cordillera*. O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd, Vancouver, BC, p161-176.
- Owens, I.F. 1972. Morphological characteristics of alpine mudflows in the Nigel Pass area. *In Mountain Geomorphology: Processes in the Canadian Cordillera*. O. Slaymaker and H. McPherson (editors). BC Geographical Series 14, Tantalus Research Ltd., Vancouver, BC, p93-100.
- Owens, I.F. 1973. Alpine mudflows in the Nigel Pass area, Canadian Rocky Mountains. PhD thesis, University of Toronto, Department of Geography, Toronto, ON, 218p.
- Thurber Consultants Ltd. 1983. Rogers Pass. Volume 2. Hydrology and debris flow potential. Report to CP Rail Special Projects, Calgary, AB.*
- Thurber Consultants Ltd. 1985. Cathedral Mountain debris flow, Report to CP Rail Special projects, Calgary AB, 37p.*
- Thurber Consultants Ltd. 1987. Debris torrent hazards along Highway 1, Sicamous to Revelstoke. Report to British Columbia Ministry of Transportation and Highways, Victoria, BC, 20p plus appendices.*
- VanDine Geological Engineering. 1990. Geological engineering assessment of the Ottawa Hill (Slocan Valley) debris torrents of May 1990. Report to British Columbia Ministry of Forests, Arrow Forest District, 16p plus appendices.*
- VanDine, D.F., Jordan, P. and Boyer, D. 1999. Perry Ridge, an example of a risk assessment for forestry planning. *In Proceedings, Confronting Uncertainty: Managing Change in Water Resources and the Environment*, Richmond, BC. Canadian Water Resources Association, BC Chapter, Vancouver, BC, p255-262.

BC Region 4: Central/North East

- Eyles, N. and Clague, J.J. 1987. Landsliding caused by Pleistocene glacial lake ponding - an example from central British Columbia. *Canadian Geotechnical Journal*, 24(4):656-663.
- Piteau Associates Ltd. 1993. Mount Goslin debris torrent hazard study, Tete Jaune Cache. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch.*

Thomson, B. 1983. Terrain features and geological processes maps and legends for the Goat-Milk River Project Area (NTS 93H/7). British Columbia Ministry of Environment, Victoria, BC.*

BC Region 5: North West

- Alley, N.F. and Thomson, B. 1978. Aspects of environmental geology, parts of Graham Island, Queen Charlotte Islands. British Columbia Ministry of Environment, Resource Analysis Branch, Victoria, BC.
- Clague, J.J. 1978. Terrain hazards in the Skeena and Kitimat River basins, British Columbia. Geological Survey of Canada, Paper 78-1A, p183-188.
- Clague, J.J., Evans, S.G. and Blown, I.G. 1985. A debris flow triggered by the breaching of a moraine-dammed lake, Klattasine Creek, British Columbia. *Canadian Journal of Earth Sciences*, 22(10):1492-1502.
- EBA Engineering Consultants Ltd. 1996. Debris flow initiation potential, gully assessment procedures, and meteorological conditions associated with debris flows in the Kalum Forest District, northwestern British Columbia. Report to Ministry of Forests, Prince Rupert Region, 32p.*
- Fannin, R.J., Wise, M.P., Wilkinson, J.M.T., Thomson, B. and Hetherington, E.D. 1997. Debris flow hazard assessment in British Columbia. *In Proceedings, 1st International Conference on Debris-flow Hazard Mitigation, San Francisco, USA.* C.-I. Chen (editor). American Society of Civil Engineers, New York, p197-206.
- Gimbarzevsky, P. 1988. Mass wasting on the Queen Charlotte Islands - a regional inventory. British Columbia Ministry of Forests, Land Management Report 29, 96p.
- Gottesfeld, A.S., Mathewes, R.W., Johnson, and Gottesfeld, L.M. 1991. Holocene debris flows and environmental history, Hazelton area, British Columbia. *Canadian Journal of Earth Sciences*, 28(10):1583-1593.
- Hogan, D.L. 1986. Channel morphology of unlogged, logged, and debris torrented streams in the Queen Charlotte Islands. British Columbia Ministry of Forests and Lands, Land Management Report 49, Victoria, BC, 94p.
- Hogan, D.L. and J.W. Schwab. 1991. Meteorological conditions associated with hillslope failures on the Queen Charlotte Islands. British Columbia Ministry of Forest, Land Management Report 73, Victoria, BC.
- Hogan, D.L., Bird, S.A. and Rice, S. 1998. Stream channel morphology and recovery processes. *In Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions.* D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Hungr, O. and Evans, S.G. 1984. An example of a peat flow near Prince Rupert, British Columbia. *Canadian Geotechnical Journal*, 22:246-249.
- Krag, R.K., Sauder, E. A. and Welburn, G.V. 1986. A forest engineering analysis of landslides in logged areas on the Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Land Management Report 43, Victoria BC, 138p.
- Mathewes, R.W. 1990. Debris flows, paleolimnology, and native oral history: A case history from British Columbia. Poster, AMQUA-CANQUA Conference, University of Waterloo, Waterloo, ON.
- Oden, M.E. 1994. Debris recharge rates in torrented gullies on the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.

- Rood, K.M. 1984. An aerial photograph inventory of frequency and yield of mass wasting on the Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Land Management Report 34, Victoria BC.
- Rood, K.M. 1990. Site characteristics and landsliding in forested and clearcut terrain, Queen Charlotte Islands, BC. British Columbia Ministry of Forests, Land Management Report 64, Victoria, BC, 46p.
- Sauder, E.A., Krag, R.K. and Wellburn, G.V. 1987. Logging and mass wasting in the Pacific Northwest with application to the Queen Charlotte Islands, BC: a literature review. British Columbia Ministry of Forests, Land Management Report 53, Victoria, BC, 26p.
- Schwab, J.W. 1983. Mass wasting: October-November 1978 storm, Rennell Sound, Queen Charlotte Islands, British Columbia. British Columbia Ministry of Forests, Research Note 91, Victoria BC.
- Schwab, J.W. 1997. Historical debris flows, British Columbia north coast. *In* Proceedings, Forestry Geotechnique and Resource Engineering, 11th Vancouver Geotechnical Society Symposium, Richmond BC.
- Schwab, J.W. 1998. Debris avalanches-flows on British Columbia's north coast. *In* Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions. D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Schwab, J.W. 1998. Landslides on the Queen Charlotte Islands: processes, rates and climatic events. *In* Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions. D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Septer, D. and Schwab, J.W. 1995. Rainstorm and flood damage: northwest British Columbia 1891-1991. British Columbia Ministry of Forests, Land Management Handbook 31, Victoria BC.
- Wilford, D.J and Schwab, J.W. 1982. Soil mass movements in the Rennell Sound area, Queen Charlotte Islands, British Columbia. *In* Proceedings, Symposium of Canadian Hydrology, Fredericton, NB, 21 p.
- Young, S.E. 1992. Analysis of slope failure and logging relationships in the Queen Charlotte Islands. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.

BC Region 6: Vancouver Island

- Askin, R.W. 1995. Mountain logging in coastal British Columbia: environmental mitigation using geotechnical principles. *In* Proceedings, 48th Canadian Geotechnical Conference, Vancouver, BC. Canadian Geotechnical Society, p745-754.
- Baumann Engineering. 1997. Level II slide assessments, Hesquiat Lake, near Boat Basin, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Baumann Engineering. 1997. Level II slide assessments, Kanim Lake, near Hotsprings Cove, British Columbia. Report to British Columbia Ministry of Forests, Port Alberni Forest District.*
- Davidson, S.C. 1998. Hydrologic controls of landsliding in Tsitika basin, Vancouver Island. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC.
- Fannin, R.J., Jaakkola, J., Wilkinson, J.M.T. and Hetherington, E.D. In press. The hydrological response of soils to rainfall at Carnation Creek, British Columbia. Water Resources Research.

- Fannin, R.J., Rollerson, T.R., Hogan, D.L. and Daust, D. 1992. Characteristics of a large debris flow channel. *In* Proceedings, Geotechnique and Natural Hazards, a Symposium, Vancouver, BC. Vancouver Geotechnical Society and Canadian Geotechnical Society, Bitech Publishers, p311-318.
- Hogan, D.L., Bird, S.A. and Rice, S. 1998. Stream channel morphology and recovery processes. *In* Proceedings, Carnation Creek and Queen Charlotte Islands Fish/Forestry Workshop: Applying 20 years of coastal research to management solutions. D.L. Hogan, P.J. Tschaplinski and S. Chatwin (editors). British Columbia Ministry of Forests, Land Management Handbook 41, Victoria BC.
- Howes, D.E. 1981. Terrain inventory and geological hazards: northern Vancouver Island. British Columbia Ministry of Environment, Assessment and Planning Division, APD Bulletin 5, Victoria, BC.
- Jakob, M. 1999. The impacts of logging on landslide activity at Clayoquot Sound, Vancouver Island, British Columbia. *Catena* 38(4):279-300.
- Lister, D.R. 1991. Debris torrent 33km north of Sayward. British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC, internal report.*
- Nasmith, H.W. and Mercer, A.G. 1979. Design of dykes to protect against debris flows at Port Alice, British Columbia. *Canadian Geotechnical Journal*, 16(4):748-757.
- Sterling, S.M. 1997. Influence of bedrock type on the magnitude, frequency and spatial distribution of debris torrents on northern Vancouver Island, BC. Masters thesis, University of British Columbia, Department of Geography, Vancouver, BC, 117 p.
- Thurber Consultants. Ltd. 1976. Port Alice Rumble Beach debris flow. Report to British Columbia Ministry of Transportation and Highways, Geotechnical and Materials Branch, Victoria, BC.*
- VanDine Geological Engineering. 1991. Kennedy Lake 1991 slope failures. Report to Fletcher Challenge Canada and MacMillan Bloedel Limited, Nanaimo, BC, 22p plus appendices.*
- VanDine Geological Engineering. 1992. Design of mitigative works for Boat Launch Creek, Kennedy Lake, BC. Report to British Columbia Ministry of Forests, Port Alberni District, Port Alberni, BC, 16p.*
- Wise, M.P. 1996. Debris flow control structure Escalante River WRP. *In* Proceedings, Coastal Forest Site Rehabilitation Workshop, BC Forestry Continuing Studies Network, Nanaimo, BC.

Manitoba

- Brevik, E.C. and Reid, J.R. 1993. Evidence for catastrophic debris flow in southern Manitoba. *In* Proceedings, North Dakota Academy of Science, 47:46.

Newfoundland

- Batterson, M., Liverman, D.G.E., Ryan, J. and Taylor, D. 1999. The assessment of geological hazards and disasters in Newfoundland: an update. Newfoundland Department of Mines and Energy, Geological Survey, Report 99-1:95-123.

Quebec

- Jacob, N. 2000. Debris flow activity in a forest environment, Gaspésie, Québec: triggering, frequency and magnitude. Masters thesis, Université Laval, Department of Geography (Centres d'Études Nordiques), Laval QU, 96p.

Yukon

- Broscoe, A.J. and Thomson, S. 1969. Observations on an alpine mudflow, Steele Creek, Yukon. *Canadian Journal of Earth Science*, 6:219-229.
- Clague, J.J. 1981. Landslides at the south end of Kluane Lake, Yukon Territory. *Canadian Journal of Earth Sciences*, 18(5):959-971.
- Gustafson, C.A. 1985. Debris flows along the Slims River valley, Kluane National Park, Yukon Territory. Masters thesis, University of Calgary, Calgary, AB.
- Harris, S.A. and Gustafson, C.A. 1993. Debris flow characteristics in an area of continuous permafrost, St. Elias Range, Yukon Territory. *Zeitschrift fur Geomorphologie*, 37(1):41-56.
- Harris, S.A. and McDermid, G. 1998. Frequency of debris flows on the Sheep Mountain fan, Kluane Lake, Yukon Territory. *Zeitschrift fur Geomorphologie*, 42(2):159-175.
- Sharp, R.P. 1942. Mudflow levees. *Journal of Geomorphology*, 5:222-227.
- Ward, B.C., Jackson, L.E. and Savigny, K.W. 1992. Evolution of Surprise Rapids landslide, Yukon Territory. Geological Survey of Canada, Paper 90-18, 25p.